Form 238-7
11/97

IDAHO DEPARTMENT OF WATER RESOURCES
WELL CONSTRUCTION REPORT

RECEIVED
JUN 25 2003
IDWR/North

OFFICE USE ONLY
Insepcted by
Twp ____ 1/4 Rge. ____ 1/4 Sec ____ 1/4
Lat. : : Long : :

1. WELL TAG NO. D 0028389
DRILLING PERMIT NO. 80-889
Other IDWR No.

2. OWNER
Name JOE AND LINDA FULTON
Address 567 BEAR ROAD
City PRIEST RIVER State ID Zip 83856

3. LOCATION OF WELL by legal description
Sketch map location must agree with written location.

N / W / E / S

Twp. 57 North (•) or South ( )
Rge. 5 East ( ) or West (•)
Sec. 23 SE 1/4 (10 acres) SE 1/4 (40 acres) ____ 1/4 (160 acres)
Gov't Lot ____ County BONNER
Lat. : :
Long : :

Address of Well SAME
City ____
(Give at least name of road + Distance to Road or Landmark)

Lt. ____ Blk. ____ Sub. Name ____

4. Use
(•)Domestic ( )Municipal ( )Monitor ( )Irrigation
( )Thermal ( )Injection ( )Other ____

5. TYPEOF WORK check all that apply (Replacement etc.)
(•)New Well ( ) Modify ( )Abandonment ( )Other ____

6. DRILL METHOD
(•)Air Rotary ( )Cable Tool ( )Mud Rotary ( )Other ____

7. SEALING PROCEDURES

SEAL / FILTER PACK Material	From	To	AMOUNT Sacks or pounds	Method
Bentonite Slurry	0	19	2 sacks	Overbore

Was drive shoe used? (•) Y ( ) N Shoe Depths(s) 301'
Was drive shoe seal tested? ( ) Y (•) N How? N/A

8. Casing / Liner

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+1	301	0.25	Steel	(•)	( )	(•)	( )
					( )	( )	( )	( )
					( )	( )	( )	( )
					( )	( )	( )	( )

Length of Headpipe N/A Length of Tailpipe N/A

9. PERFORATIONS / SCREENS
Perforations Method N/A
Screens Screen Type N/A

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
						( )	( )
						( )	( )
						( )	( )

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE
200 ft. below ground Artesian pressure N/A lb.
Depth flow encountered N/A ft. Describe access port or control devices: N/A

57 N 5W 23

11. WELL TESTS
( )Pump ( )Bailer (•)Air ( )Flowing

Yield Gal. / Min.	Drawdown	Pumping Level	Time
3.25		299'	1 Hour

Water Temp. 52 Bottom Hole Temp. ____
Water Quailty test or comments: Clear
Depth first Water 260'

12. LITHOLOGIC LOG: (Describe repairs or abandoment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
10	0	2	Topsoil		✓
10	2	35	Sand brown		✓
6	35	183	Clay - gray		✓
6	183	260	Sand - gray - fine		✓
6	260	293	Sand - brown - fine	✓	
6	293	301	Sand gravel broken rock - brown	✓	

Completed Depth 301'
Date Started 5-29-03 Completed (Measurable) 6-20-03

13. DRILLER'S CERTIFICATION
I/we certify that all minimum well construction standards were complelied with at the time the rig was removed.
Company Name Intermountain Drilling Firm No. 513
Firm Official and Driller or Operator [signature] Date 6-24-03
Date ____
(Sign once if Firm Official & operator)