RECEIVED
Form 238-7
DEC 04 2002

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

IDWR/North

OFFICE USE ONLY				
Insepcted by				
Twp.	1/4	Rge.	1/4	Sec. 1/4
Lat. : :		Long : :		

1. WELL TAG NO. D 0017911
DRILLING FERMIT NO. 27182-9
Other IDWR No.

2. OWNER
Name John Wevant
Address P.O.Box 1286
City Priest River State Id Zip 83856

POSTED

3. LOCATION OF WELL by legal description
Sketch map location must agree with written location.

N / W / E / S

Twp. 57 North ● or South ○
Rge. 4 East ○ or West ●
Sec. 8 1/4 (10 acres) SE 1/4 (40 acres) SW 1/4 (160 acres)
Gov't Lot ____ County Bonner
Lat. : :
Long : :

Address of Well Site 3/4 mile in on Blue Lake cutoff rd. on right City ____
(Give at least name of road + Distance to Road or Landmark)

Lt. ____ Blk. ____ Sub. Name ____

4. Use
● Domestic ○ Municipal ○ Monitor ○ Irrigation
○ Thermal ○ Injection ○ Other ____

5. TYPEOF WORK check all that apply (Replacement etc.)
● New Well ○ Modify ○ Abandonment ○ Other ____

6. DRILL METHOD
● Air Rotary ○ Cable Tool ○ Mud Rotary ○ Other ____

7. SEALING PROCEDURES

SEAL / FILTER PACK Material	From	To	AMOUNT Sacks or pounds	Method
Bentonite	0	19	3 sks	Overbore

Was drive shoe used? ● Y ○ N Shoe Depths(s) 198
Was drive shoe seal tested? ○ Y ● N How? ____

8. Casing / Liner

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+1'	198'	.250	Steel	●	○	●	○
					○	○	○	○
					○	○	○	○

Length of Headpipe N/A Length of Tailpipe N/A

9. PERFORATIONS / SCREENS
Perforations Method N/A
Screens Screen Type N/A

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
						○	○
						○	○
						○	○

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE
6 ft. below ground Artesian pressure N/A lb.
Depth flow enccuntered N/A ft. Describe access port or control devices: N/A

57N 4W 8

11. WELL TESTS
○ Pump ○ Bailer ● Air ○ Flowing Artesian

Yield Gal. / Min.	Drawdown	Pumping Level	Time
16 gpm		200'	1 hour

Water Temp 49 degrees Bottom Hole Temp. ____
Water Quailty test or comments: Clear
Depth first Water Encounter 123'

12. LITHOLOGIC LOG: (Describe repairs or abandoment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
10"	0	55	Sand		X
6"	55	90	Sandy clay,gray		X
	90	123	Clay, gray		X
	123	125	Silty clay with water	X	
	125	198	Clay, gray		X
	198	200	Decomposed granite	X	

Completed Depth 200' (Measurable)
Date Started 10-26-01 Completed 10-28-01

13. DRILLER'S CERTIFICATION
I/we certify that all minimum well construction standards were complelied with at the time the rig was removed.
Company Name Intermountain Drilla Firm No. 513
Firm Official _____ Date 1-11-02
and
Driller or Operator _____ Date ____
(Sign once if Firm Official & operator)