

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES
BENEFICIAL USE FIELD REPORT

A. GENERAL INFORMATION

Current owner: Cherry Creek Trees LLC
Accompanied by: N/A
Phone No:
Address:
Email:
Relationship to permit holder:

PERMIT NO

29-14314

EXAM DATE

June 15, 2021

SOURCE

Spring to Sinks

PURPOSE OF USE

Stockwater

B. OVERLAP REVIEW

Other water rights with the same place of use:

YES Overlap

Water Right No.	Source	Purpose of Use	Basis
29-7115	GROUND WATER	IRRIGATION	DECREE

Comments:

Other water rights with the same point of diversion:

No Overlap

Water Right No.	Source	Purpose of Use	Basis

Comments:

C. DIVERSION AND DELIVERY SYSTEM

LOCATION OF POINT(S) OF DIVERSION:

~~N~~ENE, Sec. 9, T12S, R37E

Metal Tag No.

New Metal Tag? No

Method of Determination: Site visit and GPS



E Back Downala Rd

Bureau of Land Management, Esri Canada, Esri, HERE, Garmin, ... Powered by Esri

Place of Use

Twp	Rng	Sec	NE				NW				SW				SE				Totals
			NE	NW	SW	SE	NE	NW	SW	SE	NE	NW	SW	SE	NE	NW	SW	SE	
				X															

Method of Determination: Site visit and GPS

- X Delivery System Diagram Attached (required). Indicate all major components and distances between components.
- X Map attached showing location(s) of point(s) of diversion and place(s) of use (required). Scale must be 1:24,000 or greater.
- X Aerial photo attached (required for irrigation of 10+ acres).
- X Photo of diversion and system attached.

D. FLOW MEASUREMENTS

Were flow measurements taken?

No

Measurement Equipment	Type	Make	Model No.	Serial No.	Size	Calib. Date

Measurement Comments:

E. FLOW CALCULATIONS

___ Additional Computation Sheets Attached

Measured Method:

Water right rate of diversion is less than 0.24 cfs. No measurement is required, Q=0.01 cfs

F. VOLUME CALCULATIONS

Volume calculations for other uses:

Other Volume Calculation:

$$\frac{40 \text{ head} \times 12 \text{ gpd} \times 365 \text{ days}}{325,850 \text{ gallons}} = 0.5 \text{ AF}$$

G. NATTATIVE/REMARKS/COMMENTS

A field exam was conducted to determine the precise location of the spring, identify the controlling works, and locate the place of use. Lyle and Janet Barnes have one spring that has been developed to support one stock water trough. The water is conveyed through an underground pipe from the spring to the trough. The spring has been developed using gravel and perforated 16 inch pipe. The water is allowed to overflow at the trough and the water sinks just west of the trough.

H. RECOMMENDATIONS

Have conditions of permit approval been met? **Yes**
If not, what condition(s) were not met?

Recommended Amounts

Beneficial Use	Period of Use	Rate of Diversion	Annual Volume
Stockwater	01/01 to 12/31	0.01 CFS	0.5 AF
	Totals:	0.01 CFS	0.5 AF

Recommended Amendments

Point of Diversion:

Place of Use:

Other Recommendations:

I. AUTHENTICATION

Field Examiner Jared Adamson

Signature

Reviewer




Date

7-1-2021

Date

7/19/2021





● 357°N (T) ● 42°23.996', -112°8.213' ±16ft ▲ 4797ft




● 326°NW (T) ● 42°24.001', -112°8.210' ±16ft ▲ 4791ft





Cherry Creek Trees LLC Beneficial Use Field Exam



0 125 250 500 Feet

