

RECEIVED

SEP 26 2016

DEPARTMENT OF
WATER RESOURCESSTATE OF IDAHO
DEPARTMENT OF WATER RESOURCES
STATEMENT OF COMPLETION
FOR SUBMITTING PROOF OF BENEFICIAL USE

FOR OFFICE USE ONLY

Amt. of Fee \$: 50
Receipt No. C102525
Receipt By: AO
Date Received: 9-26-16

The Idaho Department of Water Resources considers this form a statement by the permit holder(s) that development of a water right has been completed and that water has been applied to beneficial use to the extent described below. This form must be accompanied by an examination fee, when necessary, or by a completed Beneficial Use Field Report prepared by a certified water right examiner. Please refer to the instructions and fee schedule for this form. If ownership of the permit has changed, please contact any Department office or visit the Department's website at: www.idwr.idaho.gov for an Assignment of Permit form. If you wish to relinquish your permit because you have not established the authorized use of the water and are not applying for an extension, please notify the Department in writing.

- Permit No.: 96-9333 Telephone No.: 808-895-7211
- Name of Permit Holder(s): MARY ARMSTRONG + ROSS FULMER
CURRENT
- Mailing Address: 62-2146 OULI STREET City: KAMUELA
State: HI Zip: 96743 Email: ross-mary@hawaiiantel.net
- Source of Water: SPRING If **GROUND WATER** (well), Date Drilled: mo. ____ / yr. ____
Well Driller: N/A Drilling Permit Number: _____
- Extent of use(s) completed (as authorized by the water right permit):
Domestic (No. of households): 1 Stockwater (No. and type of stock): _____
Irrigation (No. of acres): _____ Other: _____
- Total rate of diversion or storage volume for which proof is submitted: 0.04 cfs OR _____ acre-feet.
- Compliance with a measuring device requirement, lockable controlling device requirement, and/or other conditions of permit: **Refer to the approval conditions on your permit and respond accordingly. The Department will not issue a license if permit conditions are not met.**

Measuring Device: Is a measuring device required?

Yes ☐	No ☒
Yes ☐	No ☐

If yes, has the measuring device been installed?

Lockable Controlling Device: Is a lockable device required to control the diversion?

Yes ☐	No ☒
Yes ☐	No ☐

If yes, has the lockable device been installed?

Other Conditions of Permit: Do the approval conditions on your permit require you to submit additional information in connection with your proof of beneficial use? If yes, list the conditions below and attach documents with the required information.

N/A

Completed?

Yes ☐	No ☒
------------------------------	--

- Fee Enclosed: \$ 50.00 See fee schedule on back of the instructions for filing proof of beneficial use. Proofs filed without an appropriate fee, will be considered incomplete.

- Person to contact to accompany the Department representative during field examination of the water system.

Name: MARY ARMSTRONG Telephone Number: 808-895-7211 cellPRIMARY Mailing Address: 62-2146 OULI STREET City: KAMUELAState: HI Zip: 96743 Email: marmstrong@hawaiiantel.net
or ross-mary@hawaiiantel.net

The information given on this form is my true statement of the extent to which the above numbered permit has been developed and water has been diverted and applied to a beneficial use. I understand that any undeveloped portion of the permit is relinquished to the State of Idaho.

Signature of permit holder: Mary L. Armstrong
(Include your title, if on behalf of company or organization)Date: 9/20/16

Mail to: Idaho Department of Water Resources, PO Box 83720, Boise, ID 83720-0098

water system improvements at Pack River Property



Utility trench in progress. Terminating at Cabin porch. Prior to hydrant installation



Utility trench showing water line and electrical conduit. Photo taken looking uphill toward existing house pad and existing tank location.




Beginning excavation of existing water tank.



Existing water tank exposed ready for removal.



Photo showing snow damage to existing water tank which necessitated replacement



New 1,800 gallon concrete water tank being placed in previous tank location.



Backfill at new tank underway



Final backfill being placed at new tank.



Water from new hydrant at cabin