

App 887085

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only
Inspected by _____
Twp _____ Rge _____ Sec _____
1/4 1/4 1/4
Lat : : Long: : :

1. WELL TAG NO. D 0034694

DRILLING PERMIT NO. 829853

Other IDWR No. 47-D23D6B

2. OWNER:


Name Hank C. Hafinger

Address 3772 N 1700 E

City Buhl State ID Zip 83316

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.

W  S

Twp. 11 North ☐ or South ☒
Rge. 16 East ☒ or West ☐
Sec. 6 1/4 SE 1/4 NE 1/4
Gov't Lot _____ County Twin Falls
Lat: _____ Long: _____

Address of Well Site 2200 E 3490 N

City Filer

(Give at least one of road + Distance to Road or Landmark)

LL _____ Bk. _____ Sub. Name _____

4. USE:

☐ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☒ Other commercial

5. TYPE OF WORK: check all that apply (Replacement etc.)

☐ New Well ☒ Modify ☐ Abandonment ☒ Other deepen

6. DRILL METHOD:

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES:

Seal/Filter Pack			AMOUNT Sacks or Pounds	METHOD
Material	From	To		

Was drive shoe used? ☐ Y ☒ N Shoe Depth(s) _____

Was drive shoe seal tested? ☐ Y ☒ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS:

☐ Perforations Method _____
☐ Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
						☐	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

262 ft. below ground Artesian pressure _____ ft.
Depth flow encountered _____ ft. Describe access port or control devices: _____

11. WELL TESTS:

☐ Pump ☐ Bailor ☐ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time

Water Temp. <85

Bottom hole temp. <85

Water Quality test or comments: _____

Depth first Water Encounter 361

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water	
6	355	358	medium lava	Y	N
6	358	361	soft broken lava & cinders	X	
6	361	365	medium soft		
6	365	380	medium lava		
6	380	383	soft lava & breaks	X	
6	383	390	medium lava		
6	390	394	soft lava & cinder pockers	X	
6	394	411	medium lava		
6	411	415	soft lava & breaks	X	
6	415	431	medium soft lava		
6	431	440	soft lava, cinders & breaks	X	
6	440	445	medium lava		
6	445	450	medium soft lava & breaks		

North well

RECEIVED

MAR 14 2005

Department of Water Resources
Southern Region

Completed Depth 450 (Measurable)

Date: Started 2/18/2005 Completed 2/18/2005

13. DRILLER'S CERTIFICATION:

We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Eaton Drilling & pump Service, Inc.

Firm No. 26

Firm Official Larry Wilson

Date 3/3/2005

and

Driller or Operator [Signature]

Date 3/3/2005

(Sign once if Firm Official & Operator)