

MEMORANDUM

TO: Water Right File 75-14636

FROM: Daniel Nelson – Staff Hydrologist

DATE: September 3, 2014


SUBJECT: Telephone Conversation with Shirley Hoy

On September 3, 2014, I called Shirley Hoy to determine if the lands west of the slough had been irrigated. Ms. Hoy informed me that her husband, Joseph Hoy, irrigated that ground in 2011 and 2012. He used a garden hose to go across the slough. He irrigated and mowed the ground to prevent the danger of fire in that area.




Place of Use of 75-14636.
Please note that the home
and Shop have been
constructed in this 2013
aerial photo and the field
west of the creek is being
irrigated. There is still 2.5
acres being irrigated, but
the place of use has
changed from 1987 to
2013.

2011 NAIP Photo

An aerial photograph showing a rural landscape. A large, irregular area of light brown/tan soil or dry vegetation is outlined by a green polygon. This area is situated between a dark green, forested region on the left and a more uniform light brown area on the right. A small, irregularly shaped field is located within the green-outlined area, near the forested edge. Two punch holes are visible at the top of the page.

Place of Use for 75-2091D. Please note that the home and the shop were not constructed in this 1987 aerial photo used for the determination of the 2.5 acres being irrigated. The small field west of the creek was not included in the irrigation place of use for 75-2091D.

1987 NAIP Photo



Photos provided by Amy Cassel via Dennis Ausley 08/12/14