

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES
BENEFICIAL USE FIELD REPORT

A. GENERAL INFORMATION

Permit No: 95-10023

Exam Date: 10/9/2013

1. Current Owner: TOM TORGERSON
1836 NORTHWEST BLVD
COEUR D ALENE ID 83814
(208)640-8086

2. Accompanied by:

Phone No:

Address:

Relationship to Permit Holder:

3. SOURCE

TRIBUTARY

GROUND WATER

B. OVERLAP REVIEW

1. Other water rights with the same place of use: NONE
2. Other water rights with the same point of diversion: NONE

C. DIVERSION AND DELIVERY SYSTEM**1. LOCATION OF POINT(S) OF DIVERSION:**

GROUND WATER SE1/4NE1/4 Sec. 14, Twp 53N, Rge 03W, B.M. KOOTENAI County

Method of Determination: GPS AND MAP

2.

PLACE OF USE: DOMESTIC

Twp Rge Sec	NE				NW				SW				SE				Totals
	NE	NW	SW	SE	NE	NW	SW	SE	NE	NW	SW	SE	NE	NW	SW	SE	
53N 03W 14	X	X	X	X													

PLACE OF USE: IRRIGATION

Twp Rge Sec	NE				NW				SW				SE				Totals
	NE	NW	SW	SE	NE	NW	SW	SE	NE	NW	SW	SE	NE	NW	SW	SE	
53N 03W 14	.5		3.0	1.5													5.0

Total Acres: 5

F. VOLUME CALCULATIONS

1. Volume Calculations for Irrigation:

$$V_{I.R.} = (\text{Acres Irrigated}) \times (\text{Irrigation Requirement}) = 5 \times 3\text{AF} = 15\text{AF}$$

$$V_{D.R.} = [\text{Diversion Rate (cfs)}] \times (\text{Days in Irrigation season}) \times 1.9835 = 63.67\text{AF}$$

$$V = \text{Smaller of } V_{I.R.} \text{ and } V_{D.R.} = 15\text{AF}$$

2. Volume Calculations for Other Uses: DOMESTIC 28 HOMES X 0.6AF = 16.8AF

G. NARRATIVE/REMARKS/COMMENTS

THE PWS # ID 1280069

(6) HOMEES ARE ON THIS SYSTEM AT THE DATE OF THIS EXAM. 5 ACRES OF IRRIGATION WAS LOCATED ON THE DAY OF THE EXAM. THIS IS A COMPLET SYSTEM FOR THE FIRE WITH A 4000 GALON TANK.

Have conditions of permit approval been met? ☒ Yes ☐ No

H. RECOMMENDATIONS

1. Recommended Amounts

<u>BENEFICIAL USE</u>	<u>PERIOD OF USE</u>	<u>DIVERSION RATE</u>	<u>ANNUAL VOLUME</u>
DOMESTIC	01/01 to 12/31	0.200 CFS	16.80 AF
IRRIGATION	04/01 to 10/31	0.150 CFS	15.00 AF
<u>Totals:</u>		0.200 CFS	31.80 AF

2. Recommended Amendments

☐ Change P.D. as reflected above ☐ Add P.D. as reflected above ☒ None

☐ Change P.U. as reflected above ☐ Add P.U. as reflected above ☐ Other

I. AUTHENTICATION

Field Examiner's Name Eric R. [Signature] Date 12-17-13

Reviewer Beth E. [Signature] Date 12-19-13

WELL DRILLER'S REPORT

Office Use Only			
Inspected by			
Twp. 1/4	Rge. 1/4	Sec. 1/4	
Lat.	Long.		

1. WELL TAG NO. D0040929
Drilling Permit No: 838396
Other IDWR No. 96-9235

2. OWNER **Well Number:**
Name TORGERSON, TOM **Well #1** 1076
Address 1836 NORTHWEST BLVD
City COEUR D'ALENE State ID Zip 83814

3. LOCATION OF WELL by legal description
sketch map location must agree with written location

N W S E	Twp. <u>53</u> ☒ North or ☐ South	
	Rge. <u>03</u> ☐ East or ☒ West	
	Sec. <u>14</u> <u>1/4 SE 1/4 NE 1/4</u>	
Gov't Lot _____ County <u>KOOTENAI</u>		
Lat. : : Long. : :		
Address of Well Site <u>RILEY LOOP & HWY 54</u> City <u>ATHOL</u>		

(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:

☐ Domestic ☒ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement, etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT	METHOD
Material	From	To	Sacks or Pounds	
Aqua Guard	0	60	800 lbs	TEMP CASING
BENTONITE	0	60	700 LBS	TEMP CASING

Was drive shoe used? ☐ Y ☒ N Shoe Depth(s) RB

Was drive shoe seal tested? ☐ Y ☐ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
8	+3 1/2	473	.322	STEEL	☒	☐	☒	☐

Length of Headpipe 5' Length of Tailpipe _____

9. PERFORATIONS/SCREENS

☐ Perforations Method _____
☒ Screens Screen Type STAINLESS STEEL

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
473	483	60	2	8	S/S	☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

420 ft. below ground Artesian pressure _____ lb.
Depth flow encountere _____ ft. Describe access port or
control devices: WELD ON CAP

11. WELL TESTS:

☐ Pump ☐ Bailor ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
APPROX 50+			3 1/2 HRS

Water Temp. COLD Bottom Hole Temp COLD

Water Quality test or comments: CLEAR

Depth first Water encountered 420

12. LITHOLOGIC LOG:(Describe repairs or abandonment)

					Water	
Bore Diam	From	To	Remarks: Lithology, Water Quality, Temperature	Y	N	
14	0	3	TOP SOIL	☐	☒	
14	3	60	SAND GRAVEL & COBBLE	☐	☒	
10	60	110	SAND GRAVEL & COBBLE	☐	☒	
10	110	270	SAND & GRAVEL	☐	☒	
10	270	281	SAND, GRAVEL & BOULDERS	☐	☒	
10	281	360	SAND & GRAVELS	☐	☒	
10	360	375	SAND, GRAVEL & BOULDERS	☐	☒	
10	375	420	SAND & GRAVELS	☐	☒	
10	420	483	SAND & GRAVELS	☒	☐	

RECEIVED
DEC 01 2005
IDWR/North

RECEIVED
FEB 22 2006
IDWR/North

Completed Depth 483 (Measurable)
Date: Started 11/8/2005 Completed 11/15/2005

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards
were complied with at the time the rig was removed.

Firm Name H2O Well Services, Inc. Firm No. 448

Firm Official [Signature] Date 11-22-05

and
Supervisor or Operator [Signature] Date 11/17/05

TODD MORGAN (Sign Once if Firm Official and Operator)

53N 3W 14

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT

Office Use Only			
Inspected by			
Twp	Rge	Sec	
1/4	1/4	1/4	
Lat	:	Long	:

1. WELL TAG NO. D0040928

Drilling Permit No: 836395

Other IDWR No. 96-9235

2. OWNER

Name TORGERSON, TOM WELL #2

Well Number:

1096

Address 1836 NORTHWEST BLVD

City COEUR D'ALENE State ID Zip 83814

3. LOCATION OF WELL by legal description

sketch map location must agree with written location

N
W
E
S
Twp. 53 ☒ North or ☐ South
Rge. 03 ☐ East or ☒ West
Sec. 14 1/4 SE 1/4 NE 1/4

Gov't Lot _____ County KOOTENAI

Lat: _____ Long: _____

Address of Well Site RILEY LOOP & HWY 54
City ATHOL

(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:

☐ Domestic ☒ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement, etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT	METHOD
Material	From	To	Sacks or Pounds	
3/8 HOLE PLUG	0	60	2,400 LBS	TEMP CASING

Was drive shoe used? ☐ Y ☒ N Shoe Depth(s) RB

Was drive shoe seal tested? ☐ Y ☒ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
8	+3 1/2	473	.322	STEEL	☒	☐	☒	☐

Length of Headpipe 5' Length of Tailpipe _____

9. PERFORATIONS/SCREENS

☐ Perforations Method _____
☒ Screens Screen Type STAINLESS STEEL

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
473	483	60	2	8	S/S	☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

408 ~~490~~ ft. below ground Artesian pressure _____ lb.
Depth flow encountere _____ ft. Describe access port or
control devices: _____

53 N 3 W 14

11. WELL TESTS:

☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
50+			~~22~~ HRS <u>5</u>

Water Temp. COLD Bottom Hole Temp COLD

Water Quality test or comments: CLEAR

Depth first Water encountered 420

12. LITHOLOGIC LOG:(Describe repairs or abandonment)

				Water	
Bore Diam	From	To	Remarks: Lithology, Water Quality, Temperature	Y	N
	0	0		☐	☐
14	0	3	TOP SOIL	☐	☒
14	3	60	SAND, GRAVEL & COBBLE	☐	☒
10	60	110	SAND, GRAVEL, COBBLE	☐	☒
10	110	270	SAND & GRAVEL	☐	☒
10	270	281	SAND, GRAVEL & BOULDERS	☐	☒
10	281	360	SAND & GRAVELS	☐	☒
10	360	375	SAND, GRAVEL & BOULDERS	☐	☒
10	375	420	SAND & GRAVELS	☐	☒
10	420	483	SAND & GRAVELS	☒	☐

RECEIVED
DEC 30 2005
IDWR/North

RECEIVED
FEB 22 2006
IDWR/North

Completed Depth 483 (Measurable)
Date: Started 12/9/2005 Completed 12/19/2005

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards
were complied with at the time the rig was removed.

Firm Name H2O Well Service, Inc. Firm No. 448

Firm Official Thomas R. H. H. Date 12-21-05

and
Supervisor or Operator Todd Morgan Date 12/20/05

TODD MORGAN (Sign Once if Firm Official and Operator)



PUMPS.JPG



SYSTEM.JPG



PUMP HOUSE.JPG



MAIL BOXS.JPG



SIGN_.JPG



IMG_0611.JPG



FIRE.JPG



IMG_0616.JPG



SIGN.JPG



STUB OUT.JPG



HOME #1 .JPG



HOME #2.JPG



IMG_0626.JPG



HOME #3.JPG



LAWN.JPG



HOME #4.JPG



HOME#5.JPG



HOME #6.JPG



D0040929.JPG



IMG_0645D0040928.JPG



2 POD.JPG



IMG_0648BUSTER
PUMPS.JPG



FLOW 1.JPG



FLOW 2.JPG

95-10023













95-10023

22



(6 homes) N 47 56.821
WP 208 W 116 39.846