

IN-OFFICE BENEFICIAL USE EXAM REPORT
 Permit No. 63-33488 Prepared by SCurtis Date 4/29/13

	Same as permit	Different than permit
Owner Name	☒	☐ _____
Owner Address	☒	☐ _____
Source	☒	☐ _____
Tributary	☒	☐ _____
POD	☒	☐ _____
POU	☒	☐ _____
Beneficial Use(s)	☒	☐ _____

Exam Fee Required for Permitted Rate \$ 0Exam Fee Paid \$ 0
 Overlaps ☐ Yes ☒ No - other lots
Technical Confirmation Tools

ArcMap (Bing)



Govt Agency Records

Photo

GPS ☐

Taxlot

Photos ☐

Well Log

Diagrams ☐

Other

☐ explain: _____
 Conditions/Comments _____

Exam Date Entered ☒Draft License Created ☒Shapes Updated ☒

IDAHO DEPARTMENT OF WATER RESOURCES WELL DRILLER'S REPORT

733851

Office Use Only			
Inspected by			
Twp	Rge	Sec	
1/4	1/4	1/4	
Lat	:	Long	:

1. WELL TAG NO. D 0012648
 DRILLING PERMIT NO. _____
 Other IDWR No. _____

2. OWNER:
 Name Michael Myers
 Address 6172 Latigo Dr.
 City Boise State ID Zip 83709

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.

N				
		X		

Twp. 3 North ☒ or South ☐
 Rge. 1 East ☒ or West ☐
 Sec. 36 1/4 NW 1/4 SE 1/4
 Gov't Lot _____ County Ada
 Lat: _____ Long: _____
 Address of Well Site 6172 Latigo Dr.
 City Boise

(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Bk. _____ Sub. Name _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT Sacks or Pounds	METHOD
Material	From	To		
Bentonite	0	52	1300 LB	Overbore

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 191

Was drive shoe seal tested? ☐ Y ☒ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+1.5	191	.25	Steel	☒	☐	☒	☐
5"	186	191	.25	Steel	☒	☐	☒	☐

Length of Headpipe 5 ft Length of Tailpipe -

9. PERFORATIONS/SCREENS

Perforations

Method

Screens

Screen Type Houston

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
191	196	.020	-	5"	Stainless	☐	☒

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

114 ft. below ground Artesian pressure _____ lb.
 Depth flow encountered _____ ft. Describe access port or control devices: _____

11. WELL TESTS:

☐ Pump ☐ Bailor ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
40 GPM	-	181	1 hour

Water Temp. 63° Bottom hole temp. _____

Water Quality test or comments: _____

Depth first Water Encounter 114

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
10	0	4	Hard Pan		X
"	4	6	Lava Boulders		X
"	6	52	Lava		X
"	52	90	Gravel		X
"	90	95	Tan Clay		X
"	95	105	Sand		X
"	105	114	Sandy Clay		X
"	114	130	Sand		X
"	130	142	Tan Clay		X
"	142	160	Sand	X	
"	160	180	Sandy Clay		X
"	180	185	Sand (Fine)	X	
"	185	191	Tan Clay		X
"	191	196	Sand (Coarse)	X	

RECEIVED

APR 06 2000

WATER RESOURCES
WESTERN REGION

RECEIVED

MAY 5 - 2000

Department of Water Resources

Completed Depth 196 ft (Measurable)

Date: Started 12-21-99 Completed 2-11-00

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Course Well Drilling Firm No. 4109

Firm Official Ray E. Gier Date 2-11-00

and
 Driller or Operator Andy Clark Date 2-11-00

(Sign once if Firm Official & Operator)

SWSE

36

SESE

03N01E

Taxlot Data:

Pin: R8223010470

Owner: Michael B. & Susan E. Myers

Address: 6172 S. Latigo Dr.

Boise, ID 83709

Legal: Lot 12, Blk. 17, Sunset West Subd. #2

Acres: 0.9

Year Built: 1974

NWNB 2

1

NENE 1

02N01E