



TRIP REPORT

TO: File 29-7391
CC: Craig Saxton
FROM: Kade Raymond, EIT
DATE: 9/12/2012
SUBJECT: Banks Beneficial Use Exam

Permit 29-7391

On Thursday, 8/9/2012, I visited the permit site to determine if the permit holder had installed a measuring device as instructed by the department. After walking down the creek for quite a ways I could not locate any type of weir that had been installed. Please see the pictures below to see what the creek looks like in this area.



Figure 1: View of the stream.



Figure 2: Stream is covered in willows the closer you get to chesterfield reservoir.