

8/96

INVENTORY OF DROUGHT WELLS

WATER RIGHT # 63-11702

DATE 8-26-96

POWER METER # NA

1. Well in use? ☒ No (see #2) ☐ Yes (skip #2)

2. Power on for well? ☒ No ☒ Yes

per ☒ Visual check NA Idaho Power information

3. Acceptable measuring device found? ☒ No ☐ Yes

Describe and list make/model/serial or i.d. # if applicable:

~~Flow measurement data~~

Comments

Diesel motor, submersible pump, gear drive =
Johnson PTO #138558 - BHP = 110 @ 1760rpm

4. Copies included for inventory file?

Profile Report ☒ Yes

Current version of Permit ☒ Yes

5. Condition of Approval regarding surface water delivery/use:

Condition #065 on Profile Report ☒ Long version ☒ Short version

Condition #5 (?) on Permit ☐ Long version ☒ Short version

("Long" = includes clause that can only divert from well if surface water cannot be delivered to right holder)

6. Sketch showing access to well from nearest landmarks - include nearest street address site &/or named road intersection with direction and estimated distance to well access site ("1/4 mile east of 27350 Peckham Rd, well 50' north of road by 2 large chemigation tanks").

On South Can-Alde Rd - 20' ± North of irrigation
lateral and 100' ± South of residence

7. Photograph of well attached to data form? ☐ Yes

8. Well site plotted on topo (not ortho) map & attached? ☒ Yes

9. Inspector's signature & title Neil Schulte

OVER

Newer home.

older home



concrete ditch

100'±

well + PTO gear drive



10'

motor




20'±

← Irrigation lateral

← concrete ditch



← South Caw-Ada Road



63-11702

Photo 8-26-96

