

# IDAHO DEPARTMENT OF WATER RESOURCES RECEIVED

## WELL INSPECTION FORM

SEP 13 1996

Department of Water Resources  
Southern Region

1. DRILLING PERMIT NO: none OTHER APPLICABLE NO: 47-08012

2. OWNER: Lynn Collier Phone: (208) 455-4355  
Address: 2200 N, 2134 E, Twin Falls, Idaho 83301

3. WELL LOCATION: Twp 13 S, Rge. 16 E, Sec. 18, NE 1/4 SE 1/4  
County Twin Falls (Provide sketch map and photo on reverse.)

4. DRILLER: \_\_\_\_\_ Lic. No. \_\_\_\_\_  
When Drilled? \_\_\_\_\_

5. WELL CONSTRUCTION: Turbine Capred wire Pipe  
Casing Diameter unknown inches Water tight cap? ☒ Yes ☐ No Access Port: ☒ Yes ☐ No  
Casing > 12 inches above ground? ☐ Yes ☒ No - Describe Turbine sits on pad on casing  
Depth of Casing unknown ft. Method Drilled unknown  
Condition of Well Casing: ☐ Good ☐ Fair ☐ Poor Describe unknown  
Control Valve? ☐ Yes ☒ No Pressure Gauge: ☐ Yes ☒ No  
Condition of Piping and Valving GOOD  
Auger to a depth of 0 ft. Evidence of Annular Seal ☒ Yes ☐ No Cement Pad  
Are there obvious construction problems that may be a source for contamination or waste of water?  
☐ Yes ☒ No (Describe in Remarks and Attach Photo - On Reverse)

### 6. HYDROLOGIC INFORMATION:

Depth to Static Water unknown ft. Water Temperature unknown °F  
Flowing Artesian ☐ Yes ☒ No Pressure: unknown (psi)  
Water Sample Taken? ☐ Yes ☒ No If yes, describe purpose \_\_\_\_\_  
Water Quality Measurements/Observations (Describe) \_\_\_\_\_

### 7. WELL USE:

☐ Domestic ☒ Irrigation ☐ Stock  
☐ Test ☐ Municipal ☐ Industrial  
☐ Abandoned ☐ Waste Disposal/Injection ☐ Not Used  
☐ Other: \_\_\_\_\_

8. POSSIBLE CONTAMINATION SOURCES:

Is there evidence of Chemigation? ☐ Yes ☒ No

If yes, is there a check-valve present? ☐ Yes ☒ No

Is there a possible source of contamination nearby? ☐ Yes ☒ No

If yes, what Type? \_\_\_\_\_

How far away from the well is this source? \_\_\_\_\_

9. REMARKS: This well LOOKS in good condition.  
I Feel the POP can covering the access  
PORT should be Replaced By a standard  
CAP.


Daniel H. Nelson Summer Field agent  
Signature of Dept. Representative & Title

7-30-96  
Inspection Date

PHOTOS, DRAWINGS, OTHER ATTACHMENTS:



This well is located in The  
NE 1/4 - NE 1/4 - SE 1/4 of section 18  
TOWNSHIP 13S - Range 16E



SEP 13 1996

RECEIVED