

IDAHO DEPARTMENT OF WATER RESOURCES

RECEIVED

WELL INSPECTION FORM

OCT 29 1996

Department of Water Resources
Southern Region

1. DRILLING PERMIT NO: None OTHER APPLICABLE NO: 72-07451
2. OWNER: William A. Knight / Tony Mariani Phone: (208) 327-0020
(208) 838-2313
Address: (Knight) H667, Box 723, Stanley Idaho 83278 (Mariani) 4525 N Shamrock, Boise Idaho
83713
3. WELL LOCATION: Twp 11 N, Rge. 16 E, Sec. 29, NW 1/4 SE 1/4
County CUSTER (Provide sketch map and photo on reverse.)
4. DRILLER: _____ Lic. No. _____
When Drilled? _____
5. WELL CONSTRUCTION:
Casing Diameter 6 inches Water tight cap? ☒ Yes ☐ No Access Port: ☒ Yes ☐ No
Casing > 12 inches above ground? ☒ Yes ☐ No - Describe _____
Depth of Casing unknown ft. Method Drilled unknown
Condition of Well Casing: ☒ Good ☐ Fair ☐ Poor Describe _____
Control Valve? ☐ Yes ☒ No Pressure Gauge: ☐ Yes ☐ No
Condition of Piping and Valving _____
Auger to a depth of 0 ft. Evidence of Annular Seal ☐ Yes ☒ No
Are there obvious construction problems that may be a source for contamination or waste of water?
☐ Yes ☒ No (Describe in Remarks and Attach Photo - On Reverse)
6. HYDROLOGIC INFORMATION:
Depth to Static Water unknown ft. Water Temperature unknown °F
Flowing Artesian ☐ Yes ☒ No Pressure: unknown (psi)
Water Sample Taken? ☐ Yes ☒ No If yes, describe purpose _____
Water Quality Measurements/Observations (Describe) _____
7. WELL USE:
☐ Domestic ☐ Irrigation ☐ Stock
☐ Test ☐ Municipal ☐ Industrial
☐ Abandoned ☐ Waste Disposal/Injection ☐ Not Used
☒ Other: Commercial CTailed Park

8. POSSIBLE CONTAMINATION SOURCES:

Is there evidence of Chemigation? ☐ Yes ☒ No

If yes, is there a check-valve present? ☐ Yes ☒ No

Is there a possible source of contamination nearby? ☐ Yes ☒ No

If yes, what Type? _____

How far away from the well is this source? _____

9. REMARKS: This well can only run 1 Rainbird
SPRINKLER (5/32 nozzle) for about 6 hrs before
it runs dry (see owner).

Daniel A. Nelson Summer Field Agent
Signature of Dept. Representative & Title

8-15-96
Inspection Date

PHOTOS, DRAWINGS, OTHER ATTACHMENTS:

This well is located
in the NW $\frac{1}{4}$ - NW $\frac{1}{4}$ - SE $\frac{1}{4}$
of section 29 Township-11N
Range 16E.

The well sits in the
center of the circular
R.V. Park located
at Torrey's Lodge



