

IDAHO DEPARTMENT OF WATER RESOURCES

WELL INSPECTION FORM

1. DRILLING PERMIT NO: NONE OTHER APPLICABLE NO: 47-08147
2. OWNER: MARILYN & VERLYN BROOK Phone: (208) 734-1845
Address: 3169 E 3500 N, TWIN FALLS, IDAHO 83301
3. WELL LOCATION: Twp 11 S, Rge. 17 E, Sec. 02, SW 1/4 NE 1/4
County TWIN FALLS (Provide sketch map and photo on reverse.)
4. DRILLER: UNKNOWN Lic. No. UNKNOWN
When Drilled? UNKNOWN
5. WELL CONSTRUCTION:
Casing Diameter 6 inches Water tight cap? ☐ Yes ☒ No Access Port: ☒ Yes ☐ No
Casing $\geq$ 12 inches above ground? ☐ Yes ☒ No - Describe THE CASING WAS COVERED WITH DIRT BUT IT IS LOCATED IN A WELL HOUSE
Depth of Casing UNKNOWN ft. Method Drilled UNKNOWN
Condition of Well Casing: ☐ Good ☒ Fair ☐ Poor Describe IT WAS BURIED - HARD TO TELL
Control Valve? ☒ Yes ☐ No Pressure Gauge: ☐ Yes ☒ No
Condition of Piping and Valving FAIR
Auger to a depth of 0 ft. Evidence of Annular Seal ☐ Yes ☒ No
Are there obvious construction problems that may be a source for contamination or waste of water?
☒ Yes ☐ No (Describe in Remarks and Attach Photo - On Reverse)
6. HYDROLOGIC INFORMATION:
Depth to Static Water UNKNOWN ft. Water Temperature UNKNOWN °F
Flowing Artesian ☐ Yes ☒ No Pressure: UNKNOWN (psi)
Water Sample Taken? ☐ Yes ☒ No If yes, describe purpose _____
Water Quality Measurements/Observations (Describe) _____
7. WELL USE:
☐ Domestic ☐ Irrigation ☒ Stock
☐ Test ☐ Municipal ☐ Industrial
☐ Abandoned ☐ Waste Disposal/Injection ☐ Not Used
☐ Other: _____

8. POSSIBLE CONTAMINATION SOURCES:

Is there evidence of Chemigation? ☐ Yes ☒ No

If yes, is there a check-valve present? ☐ Yes ☐ No

Is there a possible source of contamination nearby? ☒ Yes ☐ No

If yes, what Type? STOCK YARD - (There is a barrier between well & stockyard)
The only contamination would be seepage


How far away from the well is this source? 150 ft approx.

9. REMARKS: I was concerned about the casing on this
well. It looked as though dirt had blown
into well house and covered the casing.


David A. Nelson Summer Field agent
Signature of Dept. Representative & Title

4-10-97
Inspection Date

PHOTOS, DRAWINGS, OTHER ATTACHMENTS:



SCALE 1:24 000



CONTOUR INTERVAL 10 FEET
 DOTTED LINES REPRESENT 5-FOOT CONTOURS
 NATIONAL GEODETIC VERTICAL DATUM OF 1929

COMPLIES WITH U.S. GEOLOGICAL SURVEY STANDARDS FOR SPATIAL ACCURACY-CLASS 2
 FOR SALE BY U.S. GEOLOGICAL SURVEY
 DENVER, COLORADO 80225, OR RESTON, VIRGINIA 22092
 A FOLDER DESCRIBING TOPOGRAPHIC MAPS AND SYMBOLS IS AVAILABLE ON REQUEST



Pri
 har
 Sec
 har



This is the well house for well #2



This is the well for well #2.
The casing is covered with dirt.