

238(4)-1
5/33

IDAHO DEPARTMENT OF WATER RESOURCES

WELL INSPECTION FORM

1. DRILLING PERMIT NO: NONE OTHER APPLICABLE NO: 47-08382
2. OWNER: BOKMA HARRY & FLORA Phone: 543-4546
Address: 3919A NORTH 1000 EAST, BUHL
3. WELL LOCATION: Twp 10S, Rge. 14E, Sec. 17, NW 1/4 NW 1/4
County TWIN FALLS (Provide sketch map and photo on reverse.)
4. DRILLER: _____ Lic. No. _____
When Drilled? OWNER ESTIMATES DATE WELL DRILLED: 1935 ±
5. WELL CONSTRUCTION:
- Casing Diameter _____ inches Water tight cap? ☐ Yes ☐ No Access Port: ☐ Yes ☐ No
Casing $\geq$ 12 inches above ground? ☐ Yes ☒ No - Describe SEE PHOTO PG 2/2
Depth of Casing _____ ft. Method Drilled _____
Condition of Well Casing: ☐ Good ☐ Fair ☐ Poor Describe _____
Control Valve? ☐ Yes ☐ No Pressure Gauge: ☐ Yes ☐ No
Condition of Piping and Valving _____
Auger to a depth of _____ ft. Evidence of Annular Seal ☐ Yes ☐ No
Are there obvious construction problems that may be a source for contamination or waste of water?
☐ Yes ☐ No (Describe in Remarks and Attach Photo - On Reverse)
6. HYDROLOGIC INFORMATION:
- Depth to Static Water _____ ft. Water Temperature _____ °F
Flowing Artesian ☐ Yes ☐ No Pressure: 42 (psi)
Water Sample Taken? ☐ Yes ☒ No If yes, describe purpose _____
Water Quality Measurements/Observations (Describe) _____
7. WELL USE:
- | | | |
|--|---|---|
| ☒ Domestic | ☐ Irrigation | ☒ Stock |
| ☐ Test | ☐ Municipal | ☐ Industrial |
| ☐ Abandoned | ☐ Waste Disposal/Injection | ☐ Not Used |
| ☐ Other: _____ | | |

8. **POSSIBLE CONTAMINATION SOURCES:**

Is there evidence of Chemigation? ☐ Yes ☐ No

If yes, is there a check-valve present? ☐ Yes ☐ No

Is there a possible source of contamination nearby? ☐ Yes ☐ No

If yes, what Type? _____

How far away from the well is this source? _____

9. **REMARKS:** PHOTO OF WELL, ET. AL., PG. 2/2

Georgia Satterlee, WR Agent
Signature of Dept. Representative & Title

30 September 1996
Inspection Date

PHOTOS, DRAWINGS, OTHER ATTACHMENTS:

P/D=Sec 17, T10S, R14E-NW $\frac{1}{4}$, NW $\frac{1}{4}$, NW $\frac{1}{4}$
1 storage tank
42 PSI gauge

#47-08382



P/D located under the wood covering.
Below ground 10 feet+.



#47-08382 Bokma, Harry & Flora
Date of Exam: 30 Sept 1996