

IDAHO DEPARTMENT OF WATER RESOURCES

WELL INSPECTION FORM

1. DRILLING PERMIT NO: NONE OTHER APPLICABLE NO: 47-08147
2. OWNER: MARILYN & VERLYN BROOK Phone: (208) 734-1845
Address: 3169 E 3500 N, Twin Falls, Idaho 83301
3. WELL LOCATION: Twp 11S, Rge. 17E, Sec. 02, (LOT 2) NW 1/4 NE 1/4
County TWIN FALLS, (Provide sketch map and photo on reverse.)
4. DRILLER: UNKNOWN Lic. No. UNKNOWN
When Drilled? UNKNOWN
5. WELL CONSTRUCTION:
Casing Diameter 6 inches Water tight cap? ☐ Yes ☒ No Access Port: ☐ Yes ☒ No
Casing $\geq$ 12 inches above ground? ☐ Yes ☒ No - Describe TURBINE MOTOR.
Depth of Casing UNKNOWN ft. Method Drilled UNKNOWN
Condition of Well Casing: ☐ Good ☒ Fair ☐ Poor Describe There was a LOT OF CORROSION.
Control Valve? ☒ Yes ☐ No Pressure Gauge: ☐ Yes ☒ No
Condition of Piping and Valving Fair - There was a great deal OF CORROSION
Auger to a depth of 0 ft. Evidence of Annular Seal ☐ Yes ☒ No
Are there obvious construction problems that may be a source for contamination or waste of water?
☒ Yes ☐ No (Describe in Remarks and Attach Photo - On Reverse)
6. HYDROLOGIC INFORMATION:
Depth to Static Water UNKNOWN ft. Water Temperature UNKNOWN °F
Flowing Artesian ☐ Yes ☒ No Pressure: UNKNOWN (psi)
Water Sample Taken? ☐ Yes ☒ No If yes, describe purpose _____
Water Quality Measurements/Observations (Describe) _____
7. WELL USE:
☒ Domestic ☐ Irrigation ☒ Stock
☐ Test ☐ Municipal ☐ Industrial
☐ Abandoned ☐ Waste Disposal/Injection ☐ Not Used
☐ Other: _____

8. POSSIBLE CONTAMINATION SOURCES:

Is there evidence of Chemigation? ☐ Yes ☒ No

If yes, is there a check-valve present? ☐ Yes ☐ No

Is there a possible source of contamination nearby? ☐ Yes ☒ No

If yes, what Type? _____


How far away from the well is this source? _____

9. REMARKS: There were 2 things I was concerned
about. First, there was a great deal of corrosion on
the pump and piping. Second, the floor was
beginning to frost heave, leaving cracks in
the cement floor of the well house.


David A. Nelson Summer Field Agent
Signature of Dept. Representative & Title

4-10-97
Inspection Date

PHOTOS, DRAWINGS, OTHER ATTACHMENTS:



SCALE 1:24 000




CONTOUR INTERVAL 10 FEET
 DOTTED LINES REPRESENT 5-FOOT CONTOURS
 NATIONAL GEODETIC VERTICAL DATUM OF 1929


COMPLIES WITH U.S. GEOLOGICAL SURVEY STANDARDS FOR SPATIAL ACCURACY-CLASS 2
 FOR SALE BY U.S. GEOLOGICAL SURVEY
 DENVER, COLORADO 80225, OR RESTON, VIRGINIA 22092
 A FOLDER DESCRIBING TOPOGRAPHIC MAPS AND SYMBOLS IS AVAILABLE ON REQUEST



Prim
 har
 Sec
 har



This is a photo of the well house
for well #1



Frost
Heaves
in
Floor

← 3500 gal
PRESSURE
TANK

This is the well and pump for
well #1