

IDAHO DEPARTMENT OF WATER RESOURCES

WELL INSPECTION FORM

WATER RIGHT
PERMIT #

1. DRILLING PERMIT NO: ? OTHER APPLICABLE NO: 47-07870
2. OWNER: DENNIE HILL Phone: 208 785-1218
Address: 126 WEST 450 NORTH BLACKFOOT, ID 83221
3. WELL LOCATION: Twp 10S, Rge. 13E, Sec. 34, NW 1/4 NW 1/4
County TWIN FALLS (Provide sketch map and photo on reverse.)
4. DRILLER: UNKNOWN Lic. No. _____
When Drilled? _____
5. WELL CONSTRUCTION:
Casing Diameter 9 inches Water tight cap? ☒ Yes ☐ No Access Port: ☒ Yes ☐ No
Casing > 12 inches above ground? ☐ Yes ☒ No - Describe FOR 2 INCHES ABOVE GROUND (SEE PHOTO)
Depth of Casing _____ ft. Method Drilled _____
Condition of Well Casing: ☐ Good ☐ Fair ☐ Poor Describe UNKNOWN
Control Valve? ☐ Yes ☐ No Pressure Gauge: ☐ Yes ☐ No
Condition of Piping and Valving _____
Auger to a depth of _____ ft. Evidence of Annular Seal ☐ Yes ☒ No
Are there obvious construction problems that may be a source for contamination or waste of water?
☐ Yes ☒ No (Describe in Remarks and Attach Photo - On Reverse)
6. HYDROLOGIC INFORMATION:
Depth to Static Water _____ ft. Water Temperature _____ °F
Flowing Artesian ☐ Yes ☐ No Pressure: _____ (psi)
Water Sample Taken? ☐ Yes ☐ No If yes, describe purpose _____
Water Quality Measurements/Observations (Describe) _____
7. WELL USE:
☒ Domestic ☐ Irrigation ☒ Stock
☐ Test ☐ Municipal ☐ Industrial
☐ Abandoned ☐ Waste Disposal/Injection ☐ Not Used
☒ Other: COMMERCIAL (DAIRY)

8. POSSIBLE CONTAMINATION SOURCES:

Is there evidence of Chemigation? ☐ Yes ☒ No

If yes, is there a check-valve present? ☐ Yes ☐ No

Is there a possible source of contamination nearby? ☐ Yes ☒ No

If yes, what Type? _____

How far away from the well is this source? _____

9. REMARKS:

Cory Shuman
Signature of Dept. Representative & Title

E.I.T.

09/10/97

Inspection Date

PHOTOS, DRAWINGS, OTHER ATTACHMENTS:

