

IDAHO DEPARTMENT OF WATER RESOURCES

WELL INSPECTION FORM

1. DRILLING PERMIT NO: _____ OTHER APPLICABLE NO: 47-08233

2. OWNER: BOSH, WAYNE & PAMELA Phone: 736-0016
Address: 2497 POLE LINE RD E., T.F. 83301

3. WELL LOCATION: Twp 09S, Rge. 17E, Sec. 35, SE 1/4 SW 1/4
County TWIN FALLS (Provide sketch map and photo on reverse.)

4. DRILLER: AUSTIN DRILLER ? Lic. No. _____
When Drilled? 1968±?

5. WELL CONSTRUCTION:

Casing Diameter 6 inches Water tight cap? ☒ Yes ☐ No Access Port: ☒ Yes ☐ No
Casing $\geq$ 12 inches above ground? ☒ Yes ☐ No - Describe 17" o.g.
Depth of Casing _____ ft. Method Drilled _____
Condition of Well Casing: ☐ Good ☒ Fair ☒ Poor Describe _____
Control Valve? ☐ Yes ☒ No Pressure Gauge: ☐ Yes ☒ No
Condition of Piping and Valving _____
Auger to a depth of _____ ft. Evidence of Annular Seal ☐ Yes ☐ No
Are there obvious constuction problems that may be a source for contamination or waste of water?
☐ Yes ☐ No (Describe in Remarks and Attach Photo - On Reverse)

6. HYDROLOGIC INFORMATION:

Depth to Static Water _____ ft. Water Temperature _____ °F
Flowing Artesian ☐ Yes ☐ No Pressure: _____ (psi)
Water Sample Taken? ☐ Yes ☐ No If yes, describe purpose _____
Water Quality Measurements/Observations (Describe) _____

7. WELL USE:

☐ Domestic ☒ Irrigation ☐ Stock
☐ Test ☐ Municipal ☐ Industrial
☐ Abandoned ☐ Waste Disposal/Injection ☐ Not Used
☐ Other: _____

8. POSSIBLE CONTAMINATION SOURCES:

Is there evidence of Chemigation? ☐ Yes ☒ No

If yes, is there a check-valve present? ☐ Yes ☐ No

Is there a possible source of contamination nearby? ☐ Yes ☐ No

If yes, what Type? SEE REMARKS

How far away from the well is this source? _____

9. REMARKS:

*GPS A0004618
PER DAVE AUSTIN 5 NOV 97, SAYS THIS WELL IS
CONTAMINATED W/ COLIFORM. THAT IS
THE REASON FOR THE NEWER WELL
BEING DRILLED IN 1988.

G. Satterlee

Signature of Dept. Representative & Title

5 NOV 97

Inspection Date

PHOTOS, DRAWINGS, OTHER ATTACHMENTS:

SEE
*GPS A0004617 →



LOOKING S'LY