

IDAHO DEPARTMENT OF WATER RESOURCES

WELL INSPECTION FORM

1. DRILLING PERMIT NO: NONE OTHER APPLICABLE NO: 47-08376

2. OWNER: Joseph and Florence Serino Phone: (208) 326-8621
Address: 2327 E, 4000N, Filer, Idaho 83328

3. WELL LOCATION: Twp 10 S, Rge. 16 E, Sec. 09, NE 1/4 NW 1/4
County Twin Falls (Provide sketch map and photo on reverse.)

4. DRILLER: UNKNOWN Lic. No. UNKNOWN
When Drilled? UNKNOWN

5. WELL CONSTRUCTION:
Casing Diameter 6 inches Water tight cap? ☒ Yes ☐ No Access Port: ☐ Yes ☒ No
Casing $\geq$ 12 inches above ground? ☐ Yes ☒ No - Describe 6" above ground
Depth of Casing UNKNOWN ft. Method Drilled UNKNOWN
Condition of Well Casing: ☒ Good ☐ Fair ☐ Poor Describe _____
Control Valve? ☐ Yes ☒ No Pressure Gauge: ☐ Yes ☒ No
Condition of Piping and Valving GOOD
Auger to a depth of -0- ft. Evidence of Annular Seal ☐ Yes ☒ No
Are there obvious construction problems that may be a source for contamination or waste of water?
☐ Yes ☒ No (Describe in Remarks and Attach Photo - On Reverse)

6. HYDROLOGIC INFORMATION:
Depth to Static Water UNKNOWN ft. Water Temperature UNKNOWN °F
Flowing Artesian ☐ Yes ☒ No Pressure: UNKNOWN (psi)
Water Sample Taken? ☐ Yes ☒ No If yes, describe purpose _____
Water Quality Measurements/Observations (Describe) _____

7. WELL USE:
☒ Domestic ☐ Irrigation ☐ Stock
☐ Test ☐ Municipal ☐ Industrial
☐ Abandoned ☐ Waste Disposal/Injection ☐ Not Used
☐ Other: _____

POSSIBLE CONTAMINATION SOURCES:

Is there evidence of Chemigation? [] Yes ☒ No

If yes, is there a check-valve present? [] Yes ☒ No

Is there a possible source of contamination nearby? [] Yes ☒ No

If yes, what Type? _____

How far away from the well is this source? _____


9. REMARKS: The well WORKS LOOK GOOD EXCEPT
FOR Hieght OF casing above GROUND

Daniel A. Nelson Temporary agent
Signature of Dept. Representative & Title


12-23-96
Inspection Date

PHOTOS, DRAWINGS, OTHER ATTACHMENTS:

See ATTACHED SHEETS




PERMIT 47-08376 INIT Dan
T. R. S. Q/Q
P/D 105 16E 9 NW-NE-NW
SCALE 4565 Quadrangle
PHOTO ID. map BB72






This is The Pressure Tank and
Well controls FOR This Permit



This is the well and House for this permit and
The relationship between the two



This well for this permit