

IDAHO DEPARTMENT OF WATER RESOURCES

WELL INSPECTION FORM

WELL DRILLER REPORTS 1973, 1974, 1982

1. DRILLING PERMIT NO: 37-94-S-0175-000 OTHER APPLICABLE NO: 37-08216-08476

2. OWNER: SLUDER, CD & M. JOAN Phone: 788-2572
Address: PO BOX 868, BELLEVUE ID. 83313

3. WELL LOCATION: Twp 01N, Rge. 18E, Sec. 23, NW 1/4 NE 1/4
County BLAINE (Provide sketch map and photo on reverse.)

4. DRILLER: KEN SMITH Lic. No. _____
When Drilled? TAKE YOUR PICK

5. WELL CONSTRUCTION:

Casing Diameter 16 inches Water tight cap? ☒ Yes ☐ No Access Port: ☒ Yes ☐ No
Casing ≥ 12 inches above ground? ☒ Yes ☐ No - Describe 16" above ground
Depth of Casing _____ ft. Method Drilled _____
Condition of Well Casing: ☐ Good ☒ Fair ☐ Poor Describe _____
Control Valve? ☐ Yes ☐ No Pressure Gauge: ☐ Yes ☒ No
Condition of Piping and Valving _____
Auger to a depth of _____ ft. Evidence of Annular Seal ☐ Yes ☐ No
Are there obvious construction problems that may be a source for contamination or waste of water?
☐ Yes ☐ No (Describe in Remarks and Attach Photo - On Reverse)

6. HYDROLOGIC INFORMATION:

Depth to Static Water _____ ft. Water Temperature _____ °F
Flowing Artesian ☐ Yes ☐ No Pressure: _____ (psi)
Water Sample Taken? ☐ Yes ☐ No If yes, describe purpose _____
Water Quality Measurements/Observations (Describe) _____

7. WELL USE:

☐ Domestic ☐ Irrigation ☐ Stock
☐ Test ☐ Municipal ☐ Industrial
☐ Abandoned ☐ Waste Disposal/Injection ☐ Not Used
☐ Other: NO PUMP

8. POSSIBLE CONTAMINATION SOURCES:

Is there evidence of Chemigation? ☐ Yes ☒ No

If yes, is there a check-valve present? ☐ Yes ☐ No

Is there a possible source of contamination nearby? ☐ Yes ☐ No

If yes, what Type? _____

How far away from the well is this source? _____

9.

REMARKS: WELL DRILLED BECAUSE THE FIRST ONE DRIED UP,
YET AFTER THIS ONE DRILLED THE OTHER ONE CAME
BACK. SLUDER SAYS HE'LL TIE IT IN TO OTHER TWO
WELLS EVENTUALLY.

Satterlee, GJ Agent

Signature of Dept. Representative & Title

14 July 97

Inspection Date

PHOTOS, DRAWINGS, OTHER ATTACHMENTS:

WELL 75' SW from Sluder's home.



NO PUMP... YET

GPS A0002908

LOOKING WEST