

IDAHO DEPARTMENT OF WATER RESOURCES

WELL INSPECTION FORM

- A37-12290
1. DRILLING PERMIT NO: UNKNOWN OTHER APPLICABLE NO: 37-08519
2. OWNER: John Bryson & Louise Henry Phone: (213) 683-9193
Address: 70 Tom Walper, 355 S. Grand Ave. 35th Floor, LA., CA. 90071
3. WELL LOCATION: Twp 05N, Rge. 17E, Sec. 10, SE 1/4 NW 1/4
County BLAINE (Provide sketch map and photo on reverse.)
4. DRILLER: KEN SMITH ± Lic. No. _____
When Drilled? 1989 ±
5. WELL CONSTRUCTION:
Casing Diameter 6 Inches Water tight cap? ☒ Yes ☐ No Access Port: ☒ Yes ☐ No
Casing ≥ 12 inches above ground? ☐ Yes ☒ No - Describe 10" o.g.
Depth of Casing _____ ft. Method Drilled _____
Condition of Well Casing: ☐ Good ☒ Fair ☐ Poor Describe _____
Control Valve? ☐ Yes ☐ No Pressure Gauge: ☒ Yes ☐ No
Condition of Piping and Valving _____
Auger to a depth of _____ ft. Evidence of Annular Seal ☐ Yes ☐ No
Are there obvious construction problems that may be a source for contamination or waste of water?
☐ Yes ☐ No (Describe in Remarks and Attach Photo - On Reverse)
6. HYDROLOGIC INFORMATION:
Depth to Static Water 15 ft. Water Temperature _____ °F
Flowing Artesian ☐ Yes ☒ No Pressure: 125 (psi)
Water Sample Taken? ☐ Yes ☒ No If yes, describe purpose _____
Water Quality Measurements/Observations (Describe) _____
7. WELL USE:
☒ Domestic ☒ Irrigation ☐ Stock
☐ Test ☐ Municipal ☐ Industrial
☐ Abandoned ☐ Waste Disposal/Injection ☐ Not Used
☐ Other: _____

8. POSSIBLE CONTAMINATION SOURCES:

Is there evidence of Chemigation? ☐ Yes ☒ No

If yes, is there a check-valve present? ☐ Yes ☒ No

Is there a possible source of contamination nearby? ☐ Yes ☒ No

If yes, what Type? _____

How far away from the well is this source? _____

9.

REMARKS:

No GPS tag or location by GPS


Georgia Satterlee

Signature of Dept. Representative & Title

15 July 98

Inspection Date

PHOTOS, DRAWINGS, OTHER ATTACHMENTS:



INSIDE
PUMPHOUSE;
PUMPHOUSE IS
IN FRONT OF
HOUSE;
HOUSE IS @ 158 BARLOW RD.