

IDAHO DEPARTMENT OF WATER RESOURCES

WELL INSPECTION FORM

1. DRILLING PERMIT NO: NONE FD. OTHER APPLICABLE NO: 37-08474
2. OWNER: Grove Crk Assn. 90 Wm. Swaney Phone: (208) 788-4550
Address: PO BX 2713, KETCHUM, ID. 83340
3. WELL LOCATION: Twp 3N, Rge. 18E, Sec. 8, NW 1/4 SW 1/4
County BLAINE (Provide sketch map and photo on reverse.)
4. DRILLER: WALKER WATER SYSTEM Lic. No. _____
When Drilled? 1984+
5. WELL CONSTRUCTION:
Casing Diameter 8" inches Water tight cap? ☒ Yes ☐ No Access Port: ☒ Yes ☐ No
Casing $\geq$ 12 inches above ground? ☒ Yes ☐ No - Describe 20' o.g.
Depth of Casing _____ ft. Method Drilled _____
Condition of Well Casing: ☒ Good ☐ Fair ☐ Poor Describe _____
Control Valve? ☐ Yes ☐ No Pressure Gauge: ☒ Yes ☐ No
Condition of Piping and Valving _____
Auger to a depth of _____ ft. Evidence of Annular Seal ☐ Yes ☐ No
Are there obvious construction problems that may be a source for contamination or waste of water?
☐ Yes ☒ No (Describe in Remarks and Attach Photo - On Reverse)
6. HYDROLOGIC INFORMATION:
Depth to Static Water _____ ft. Water Temperature _____ °F
Flowing Artesian ☐ Yes ☒ No Pressure: 50-70 (psi)
Water Sample Taken? ☐ Yes ☒ No If yes, describe purpose _____
Water Quality Measurements/Observations (Describe) _____
7. WELL USE:
☒ Domestic ☒ Irrigation ☐ Stock
☐ Test ☐ Municipal ☐ Industrial
☐ Abandoned ☐ Waste Disposal/Injection ☐ Not Used
☐ Other: HOME / 2.5 ACRES IRR.

8. POSSIBLE CONTAMINATION SOURCES:

Is there evidence of Chemigation? ☐ Yes ☒ No

If yes, is there a check-valve present? ☐ Yes ☒ No

Is there a possible source of contamination nearby? ☐ Yes ☒ No

If yes, what Type? _____

How far away from the well is this source? _____

9. REMARKS: WELL IS ON LOT 2 OF GROVE CREEK SUBD.

J. Satterlee

Signature of Dept. Representative & Title

15 Sept 97

Inspection Date

PHOTOS, DRAWINGS, OTHER ATTACHMENTS:

150' S'LY OF P/D
EAST FORK BIG WOOD FLOW



PHOTO LOOKING E'LY

PHOTO LOOKING S'LY