

IDAHO DEPARTMENT OF WATER RESOURCES

WELL INSPECTION FORM

1. DRILLING PERMIT NO: _____ OTHER APPLICABLE NO: 37-08575B
2. OWNER: City of Ketchum Phone: _____
Address: 4800 East Ave N., Ketchum, ID 83340
3. WELL LOCATION: Twp 04N, Rge. 17E, Sec. 12, SW 1/4 SE 1/4
County BLAINE (Provide sketch map and photo on reverse.)
4. DRILLER: _____ Lic. No. _____
When Drilled? ?
5. WELL CONSTRUCTION:
Casing Diameter 8 inches Water tight cap? ☒ Yes ☐ No Access Port: ☒ Yes ☐ No
Casing $\geq$ 12 inches above ground? ☒ Yes ☐ No - Describe 12"
Depth of Casing _____ ft. Method Drilled _____
Condition of Well Casing: ☐ Good ☐ Fair ☐ Poor Describe _____
Control Valve? ☐ Yes ☐ No Pressure Gauge: ☐ Yes ☒ No Not Working
Condition of Piping and Valving _____
Auger to a depth of _____ ft. Evidence of Annular Seal ☐ Yes ☐ No
Are there obvious construction problems that may be a source for contamination or waste of water?
☐ Yes ☐ No (Describe in Remarks and Attach Photo - On Reverse)
6. HYDROLOGIC INFORMATION:
Depth to Static Water _____ ft. Water Temperature _____ °F
Flowing Artesian ☐ Yes ☐ No Pressure: _____ (psi)
Water Sample Taken? ☐ Yes ☐ No If yes, describe purpose _____
Water Quality Measurements/Observations (Describe) _____
7. WELL USE:
☒ Domestic ☒ Irrigation ☐ Stock
☐ Test ☒ Municipal ☐ Industrial
☐ Abandoned ☐ Waste Disposal/Injection ☐ Not Used
☐ Other: _____

8. **POSSIBLE CONTAMINATION SOURCES:**

Is there evidence of Chemigation? ☐ Yes ☐ No

If yes, is there a check-valve present? ☐ Yes ☐ No

Is there a possible source of contamination nearby? ☐ Yes ☐ No

If yes, what Type? _____

How far away from the well is this source? _____

9. **REMARKS:**

AKA "NORTHWOOD WELL"
SEE PHOTOS for GPS #

GSatterlee

Signature of Dept. Representative & Title


3 June 98

Inspection Date

PHOTOS, DRAWINGS, OTHER ATTACHMENTS:

see attached sh. w/ photos

South
Pump
house
(locked)



LOOKING W/LY

GPS tag




LOOKING E/LY

6 3 '98



GPS A0007813



6 3 '98