

IDAHO DEPARTMENT OF WATER RESOURCES

WELL INSPECTION FORM

1. DRILLING PERMIT NO: ? OTHER APPLICABLE NO: 37-08480
2. OWNER: La Peter Alfred R. Phone: 726-7888
Address: PO Box 38010
3. WELL LOCATION: Twp 04N, Rge. 17E, Sec. 01, NW 1/4 SE 1/4
County BLAINE (Provide sketch map and photo on reverse.)
4. DRILLER: ROESSLER Lic. No. _____
When Drilled? 1984±
5. WELL CONSTRUCTION:
Casing Diameter 6" inches Water tight cap? ☒ Yes ☐ No Access Port: ☒ Yes ☐ No
Casing $\geq$ 12 inches above ground? ☐ Yes ☒ No - Describe 7"
Depth of Casing _____ ft. Method Drilled _____
Condition of Well Casing: ☐ Good ☐ Fair ☐ Poor Describe _____
Control Valve? ☐ Yes ☐ No Pressure Gauge: ☐ Yes ☐ No
Condition of Piping and Valving _____
Auger to a depth of _____ ft. Evidence of Annular Seal ☐ Yes ☐ No
Are there obvious construction problems that may be a source for contamination or waste of water?
☐ Yes ☐ No (Describe in Remarks and Attach Photo - On Reverse)
6. HYDROLOGIC INFORMATION:
Depth to Static Water _____ ft. Water Temperature _____ °F
Flowing Artesian ☐ Yes ☒ No Pressure: _____ (psi)
Water Sample Taken? ☐ Yes ☒ No If yes, describe purpose _____
Water Quality Measurements/Observations (Describe) _____
7. WELL USE:
☒ Domestic ☒ Irrigation ☐ Stock
☐ Test ☐ Municipal ☐ Industrial
☐ Abandoned ☐ Waste Disposal/Injection ☐ Not Used
☒ Other: AESTHETIC

8. POSSIBLE CONTAMINATION SOURCES:

Is there evidence of Chemigation? ☐ Yes ☒ No

If yes, is there a check-valve present? ☐ Yes ☒ No

Is there a possible source of contamination nearby? ☐ Yes ☒ No

If yes, what Type? _____

How far away from the well is this source? _____

9. REMARKS: P/D on Lot 1 of Riverwoods Subdivision

DSatterlee
Signature of Dept. Representative & Title

190c498
Inspection Date

PHOTOS, DRAWINGS, OTHER ATTACHMENTS:



GPS Tag
A0007838

Photo Looking NW'ly