

IDAHO DEPARTMENT OF WATER RESOURCES

WELL INSPECTION FORM

1. DRILLING PERMIT NO: END. WELL DRILLER REPORT ONLY OTHER APPLICABLE NO: 37-08427
2. OWNER: Robert N. Ruth Phone: (310) 526-1518
Address: 1150 Santa Monica, Ste. 200, L.A., CA. 90025
3. WELL LOCATION: Twp 03N, Rge. 18E, Sec. 07, SE 1/4, NE 1/4
County BLAINE (Provide sketch map and photo on reverse.)
4. DRILLER: ROESSLER Lic. No. _____
When Drilled? 1981
5. WELL CONSTRUCTION:
Casing Diameter 6 inches Water tight cap? ☒ Yes ☐ No Access Port: ☒ Yes ☐ No
Casing $\geq$ 12 inches above ground? ☒ Yes ☐ No - Describe 17" o.g.
Depth of Casing _____ ft. Method Drilled _____
Condition of Well Casing: ☐ Good ☒ Fair ☐ Poor Describe _____
Control Valve? ☐ Yes ☐ No Pressure Gauge: ☒ Yes ☐ No
Condition of Piping and Valving _____
Auger to a depth of _____ ft. Evidence of Annular Seal ☐ Yes ☐ No
Are there obvious construction problems that may be a source for contamination or waste of water?
☐ Yes ☐ No (Describe in Remarks and Attach Photo - On Reverse)
6. HYDROLOGIC INFORMATION:
Depth to Static Water _____ ft. Water Temperature _____ °F
Flowing Artesian ☐ Yes ☐ No Pressure: _____ (psi)
Water Sample Taken? ☐ Yes ☒ No If yes, describe purpose _____
Water Quality Measurements/Observations (Describe) _____
7. WELL USE:
☐ Domestic ☒ Irrigation ☐ Stock
☐ Test ☐ Municipal ☐ Industrial
☐ Abandoned ☐ Waste Disposal/Injection ☐ Not Used
☐ Other: _____

8. POSSIBLE CONTAMINATION SOURCES:

Is there evidence of Chemigation? ☐ Yes ☒ No

If yes, is there a check-valve present? ☐ Yes ☐ No

Is there a possible source of contamination nearby? ☐ Yes ☐ No

If yes, what Type? _____

How far away from the well is this source? _____

AKA

9. REMARKS: LOT 15, GIMLET SUBD. NO. 11

(A37-11839 LOT 16)

G. L. Satterlee

Signature of Dept. Representative & Title

29 Sept 97

Inspection Date

PHOTOS, DRAWINGS, OTHER ATTACHMENTS:

GPS Tag A0002839



Photo looking E'ly