

IDAHO DEPARTMENT OF WATER RESOURCES
WELL INSPECTION FORM

WELL DRILLER REPORT UNDER: (A)37-08200

1. DRILLING PERMIT NO: DALE DONNLEY OTHER APPLICABLE NO: 37-08200

2. OWNER: PATRICIA HANSING Phone: 788-4664
Address: PD Bx 1298, HAILEY, ID. 83333

3. WELL LOCATION: Twp 02N, Rge. 18E, Sec. 5, NE 1/4 SE 1/4
County BLAINE (Provide sketch map and photo on reverse.)

4. DRILLER: _____ Lic. No. _____
When Drilled? 1977±

5. WELL CONSTRUCTION:
Casing Diameter 6 inches? Water tight cap? ☒ Yes ☐ No Access Port: ☒ Yes ☐ No
Casing ≥ 12 inches above ground? ☐ Yes ☒ No - Describe FLUSH w/ O.G.
Depth of Casing _____ ft. Method Drilled _____
Condition of Well Casing: ☐ Good ☐ Fair ☐ Poor Describe CAN'T TELL
Control Valve? ☐ Yes ☐ No Pressure Gauge: ☒ Yes ☐ No
Condition of Piping and Valving _____
Auger to a depth of _____ ft. Evidence of Annular Seal ☐ Yes ☐ No
Are there obvious constuction problems that may be a source for contamination or waste of water?
☐ Yes ☐ No (Describe in Remarks and Attach Photo - On Reverse)

6. HYDROLOGIC INFORMATION:
Depth to Static Water _____ ft. Water Temperature _____ °F
Flowing Artesian ☐ Yes ☐ No Pressure: 65 (psi)
Water Sample Taken? ☐ Yes ☒ No If yes, describe purpose _____
Water Quality Measurements/Observations (Describe) _____

7. WELL USE:
☒ Domestic ☒ Irrigation ☐ Stock
☐ Test ☐ Municipal ☐ Industrial
☐ Abandoned ☐ Waste Disposal/Injection ☐ Not Used
☐ Other: _____

8. POSSIBLE CONTAMINATION SOURCES:

Is there evidence of Chemigation? ☐ Yes ☒ No

If yes, is there a check-valve present? ☐ Yes ☐ No

Is there a possible source of contamination nearby? ☐ Yes ☐ No

If yes, what Type? _____

How far away from the well is this source? _____

9. REMARKS:

40' EAST of WEST PROPERTY LINE
3' NORTH of PINE TREE
10' SOUTH of SW COR. of DUMPHOUSE

Spatterlee WR Agent

Signature of Dept. Representative & Title

13 Aug 97

Inspection Date

PHOTOS, DRAWINGS, OTHER ATTACHMENTS:

GPS A0002941



PHOTO LOOKING S'LY