

IDAHO DEPARTMENT OF WATER RESOURCES

RECEIVED WELL INSPECTION FORM

AUG 05 1997

Department of Water Resources
Southern Region

1. DRILLING PERMIT NO: N/A APPLICABLE NO: A37-10597

2. OWNER: Faulkner Land & Livestock Phone: 934 4956
Address: Rt 2 Gooding

3. WELL LOCATION: Twp 6S, Rge. 1SE, Sec. 7, SW NE OR NW NE 1/4 1/4
County GOODING (Provide sketch map and photo on reverse.)

4. DRILLER: ? Lic. No. _____
When Drilled? _____

5. WELL CONSTRUCTION:


Casing Diameter 6 inches Water tight cap? ☐ Yes ☒ No Access Port: ☐ Yes ☒ No
Casing $\geq$ 12 inches above ground? ☐ Yes ☒ No - Describe Wellhead below grade in pit
Depth of Casing N/A ft. Method Drilled _____
Condition of Well Casing: ☐ Good ☐ Fair ☐ Poor Describe _____
Control Valve? ☐ Yes ☐ No Pressure Gauge: ☐ Yes ☐ No
Condition of Piping and Valving _____
Auger to a depth of _____ ft. Evidence of Annular Seal ☐ Yes ☐ No
Are there obvious construction problems that may be a source for contamination or waste of water?
☒ Yes ☐ No (Describe in Remarks and Attach Photo - On Reverse)

6. HYDROLOGIC INFORMATION: N/A

Depth to Static Water _____ ft. Water Temperature _____ °F
Flowing Artesian ☐ Yes ☐ No Pressure: _____ (psi)
Water Sample Taken? ☐ Yes ☐ No If yes, describe purpose _____
Water Quality Measurements/Observations (Describe) _____

7. WELL USE:

☒ Domestic ☐ Irrigation ☒ Stock
☐ Test ☐ Municipal ☐ Industrial
☐ Abandoned ☐ Waste Disposal/Injection ☐ Not Used
☐ Other: _____



8. POSSIBLE CONTAMINATION SOURCES:

Is there evidence of Chemigation? ☐ Yes ☒ No

If yes, is there a check-valve present? ☐ Yes ☐ No

Is there a possible source of contamination nearby? ☐ Yes ☐ No

If yes, what Type? _____

How far away from the well is this source? _____

9.

REMARKS: wellhead and all plumbing in pit. Situated in
pasture/irrigated area.

Cindy J. Hodges

Signature of Dept. Representative & Title

6-24-97

Inspection Date

PHOTOS, DRAWINGS, OTHER ATTACHMENTS:

