

IDAHO DEPARTMENT OF WATER RESOURCES

WELL INSPECTION FORM

- A37-11052
1. DRILLING PERMIT NO: _____ OTHER APPLICABLE NO: 37-07415
2. OWNER: TURNER, CHAS. & STALEY Phone: 934-8384
Address: 1747 E. 1700 S. GOODING, ID. 83330
3. WELL LOCATION: Twp 05S, Rge. 4E, Sec. 36, NE 1/4 NW 1/4
County GOODING (Provide sketch map and photo on reverse.)
4. DRILLER: _____ Lic. No. _____
When Drilled? _____
5. WELL CONSTRUCTION:
Casing Diameter _____ inches Water tight cap? ☒ Yes ☐ No Access Port: ☒ Yes ☐ No
Casing $\geq$ 12 inches above ground? ☒ Yes ☐ No - Describe _____
Depth of Casing _____ ft. Method Drilled _____
Condition of Well Casing: ☐ Good ☒ Fair ☒ Poor Describe _____
Control Valve? ☐ Yes ☐ No Pressure Gauge: ☒ Yes ☐ No
Condition of Piping and Valving _____
Auger to a depth of _____ ft. Evidence of Annular Seal ☐ Yes ☐ No
Are there obvious construction problems that may be a source for contamination or waste of water?
☐ Yes ☐ No (Describe in Remarks and Attach Photo - On Reverse)
6. HYDROLOGIC INFORMATION:
Depth to Static Water _____ ft. Water Temperature _____ °F
Flowing Artesian ☐ Yes ☐ No Pressure: 52 (psi)
Water Sample Taken? ☐ Yes ☐ No If yes, describe purpose _____
Water Quality Measurements/Observations (Describe) _____
7. WELL USE:
☐ Domestic ☒ Irrigation ☐ Stock
☐ Test ☐ Municipal ☐ Industrial
☐ Abandoned ☐ Waste Disposal/Injection ☐ Not Used
☐ Other: _____

8. POSSIBLE CONTAMINATION SOURCES:

Is there evidence of Chemigation? ☐ Yes ☒ No

If yes, is there a check-valve present? ☐ Yes ☐ No

Is there a possible source of contamination nearby? ☐ Yes ☐ No

If yes, what Type? _____

How far away from the well is this source? _____

9.

REMARKS: THE GPS LOCATION PERFORMED BY:
JEFF MARTIN @ NORTH SNAKE GROUND WATER DIST.

Georgia Satterlee WEA
Signature of Dept. Representative & Title

18 Aug 97
Inspection Date

PHOTOS, DRAWINGS, OTHER ATTACHMENTS:

GPS A0005559



LOOKING WEST



LOOKING NORTH

FLOW MTR. NOT WORKING