


IDAHO DEPARTMENT OF WATER RESOURCES

WELL INSPECTION FORM

1. DRILLING PERMIT NO: None OTHER APPLICABLE NO: 71-07109
2. OWNER: STAN HARRAH CORPORATION Phone: (702) 323-4526
Address: P.O. Box 12968, Reno, Nevada 89510-2968
3. WELL LOCATION: Twp 10N, Rge. 13E, Sec. 10, ^{Lot #2} NW 1/4 NW 1/4
County CUSTER (Provide sketch map and photo on reverse.)
4. DRILLER: UNKNOWN Lic. No. UNKNOWN
When Drilled? UNKNOWN
5. WELL CONSTRUCTION:
Casing Diameter 8 inches Water tight cap? ☒ Yes ☐ No Access Port: ☒ Yes ☐ No
Casing $\geq$ 12 inches above ground? ☒ Yes ☐ No - Describe _____
Depth of Casing unknown ft. Method Drilled unknown
Condition of Well Casing: ☐ Good ☒ Fair ☐ Poor Describe _____
Control Valve? ☐ Yes ☒ No Pressure Gauge: ☐ Yes ☒ No
Condition of Piping and Valving Fair
Auger to a depth of 0 ft. Evidence of Annular Seal ☐ Yes ☒ No
Are there obvious construction problems that may be a source for contamination or waste of water?
☒ Yes ☐ No (Describe in Remarks and Attach Photo - On Reverse)
6. HYDROLOGIC INFORMATION:
Depth to Static Water unknown ft. Water Temperature unknown °F
Flowing Artesian ☐ Yes ☒ No Pressure: unknown (psi)
Water Sample Taken? ☐ Yes ☒ No If yes, describe purpose N/A
Water Quality Measurements/Observations (Describe) N/A
7. WELL USE:
☐ Domestic ☐ Irrigation ☐ Stock
☐ Test ☐ Municipal ☐ Industrial
☐ Abandoned ☐ Waste Disposal/Injection ☐ Not Used
☒ Other: commercial (Hotel & Restaurant)



8. POSSIBLE CONTAMINATION SOURCES:

Is there evidence of Chemigation? [] Yes [X] No

If yes, is there a check-valve present? [] Yes [X] No

Is there a possible source of contamination nearby? [] Yes [X] No

If yes, what Type? N/A

How far away from the well is this source? N/A

9.

REMARKS: This well had water standing in
the bottom of the well pit. This could be
a problem in the future.

Daniel A. Nelson Summer Field Agent
Signature of Dept. Representative & Title

~~8-14-96~~ 8-14-96
Inspection Date

PHOTOS, DRAWINGS, OTHER ATTACHMENTS:

