

IDAHO DEPARTMENT OF WATER RESOURCES

WELL INSPECTION FORM

1. DRILLING PERMIT NO: _____ OTHER APPLICABLE NO: 36-10452
36-08768
2. OWNER: ALLEN KARLA MOYLE Phone: 536-6739
Address: 3539 S 1500 E WENDELL ID 83355
3. WELL LOCATION: Twp 08S, Rge. 14E, Sec. 34, SE 1/4 NE 1/4
County GOODING (Provide sketch map and photo on reverse.)
4. DRILLER: DALE GILBERT Lic. No. _____
When Drilled? 1979 ±
5. WELL CONSTRUCTION:
Casing Diameter 8 inches Water tight cap? ☒ Yes ☐ No Access Port: ☒ Yes ☐ No
Casing ≥ 12 inches above ground? ☐ Yes ☒ No - Describe 6" o.g.
Depth of Casing _____ ft. Method Drilled _____
Condition of Well Casing: ☐ Good ☒ Fair ☒ Poor Describe _____
Control Valve? ☐ Yes ☐ No Pressure Gauge: ☒ Yes ☐ No
Condition of Piping and Valving _____
Auger to a depth of _____ ft. Evidence of Annular Seal ☐ Yes ☐ No
Are there obvious construction problems that may be a source for contamination or waste of water?
☐ Yes ☐ No (Describe in Remarks and Attach Photo - On Reverse)
6. HYDROLOGIC INFORMATION:
Depth to Static Water 80± ft. Water Temperature _____ °F
Flowing Artesian ☐ Yes ☐ No Pressure: 45 (psi)
Water Sample Taken? ☐ Yes ☐ No If yes, describe purpose _____
Water Quality Measurements/Observations (Describe) _____
7. WELL USE:
☒ Domestic ☐ Irrigation ☒ Stock
☐ Test ☐ Municipal ☐ Industrial
☐ Abandoned ☐ Waste Disposal/Injection ☐ Not Used
☐ Other: MINK FARM

8. POSSIBLE CONTAMINATION SOURCES:

Is there evidence of Chemigation? ☐ Yes ☒ No

If yes, is there a check-valve present? ☐ Yes ☐ No

Is there a possible source of contamination nearby? ☐ Yes ☐ No

If yes, what Type? _____

How far away from the well is this source? _____

9. REMARKS:

JP Satterlee

Signature of Dept. Representative & Title

18 Dec 1997

Inspection Date

PHOTOS, DRAWINGS, OTHER ATTACHMENTS:



#1 WELL

-GPS A0004648

2HP pump

PHOTO LOOKING S'LY