

IDAHO DEPARTMENT OF WATER RESOURCES
WELL INSPECTION FORM

787141

1. DRILLING PERMIT NO: 787141 OTHER APPLICABLE NO: Tag# D0023382
2. OWNER: Nunes Brothers Dairy Phone: 536-6579
Address: 2933-A S 1500 E Wendell Ida 83355
3. WELL LOCATION: Twp D7S Rge. 14E Sec. 35 NW 1/4 SW 1/4
County App. 3020 S 1500 E Gooding (Provide sketch map and photo on reverse.)
4. DRILLER: Eaton Drilling & Pump Lic. No. 26
When Drilled? Sept 27-2002
5. WELL CONSTRUCTION:
Casing Diameter 8 inches Water tight cap? ☒ Yes ☐ No Access Port: ☒ Yes ☐ No
Casing $\geq$ 12 inches above ground? ☒ Yes ☐ No - Describe _____
Depth of Casing 123 ft. Method Drilled Air Rotary
Condition of Well Casing: ☒ Good ☐ Fair ☐ Poor Describe _____
Control Valve? ☐ Yes ☒ No Pressure Gauge: ☐ Yes ☒ No
Condition of Piping and Valving _____
Auger to a depth of 123 ft. Evidence of Annular Seal ☒ Yes ☐ No
Are there obvious constuction problems that may be a source for contamination or waste of water?
☐ Yes ☒ No (Describe in Remarks and Attach Photo - On Reverse)
6. HYDROLOGIC INFORMATION:
Depth to Static Water 78 ft. Water Temperature _____ of
Flowing Artesian ☐ Yes ☒ No Pressure: _____ (psi)
Water Sample Taken? ☐ Yes ☒ No If yes, describe purpose _____
Water Quality Measurements/Observations (Describe) _____
7. WELL USE:
☒ Domestic ☐ Irrigation ☐ Stock
☐ Test ☐ Municipal ☐ Industrial
☐ Abandoned ☐ Waste Disposal/Injection ☐ Not Used
☐ Other: _____

8. **POSSIBLE CONTAMINATION SOURCES:**

Is there evidence of Chemigation? ☐ Yes ☒ No

If yes, is there a check-valve present? ☐ Yes ☒ No

Is there a possible source of contamination nearby? ☐ Yes ☒ No

If yes, what Type? _____


How far away from the well is this source? _____

9.

REMARKS:

GPS 0435277
0186682

wrong legal Sent out letter
12-09-02 nwnw


Signature of Dept. Representative & Title

12-09-02
Inspection Date

PHOTOS, DRAWINGS, OTHER ATTACHMENTS: