



State of Idaho

DEPARTMENT OF WATER RESOURCES

Northern Region, 7600 Mineral Drive, Suite 100, Coeur d'Alene, Idaho 83815

Phone: (208) 762-2800 FAX: (208) 762-2819 www.idwr.idaho.gov

C.L. "BUTCH" OTTER
Governor

DAVID R. TUTHILL, JR
Director

September 4, 2008
ROSE LAKE WATER ASSOCIATION
P.O. BOX 178
CATALDO, ID 83810-0178

Re: Application for Water License to appropriate the Public Waters of the State of Idaho:
Water Right Number 94-7367.

After reviewing the water permit and well driller's reports for this license we have discovered that fee for your well needs and upgrade. I have enclosed copies of the driller report that indicate domestic use only in line #4. This means the driller bought two permits for \$ 35.00 in 1994, 1996 for domestic use (Not Municipal). The one time well upgrade fee is \$165.00 for each Municipal. The driller bought one permits for \$ 75.00 in 1997 for domestic use (Not Municipal). The one time well upgrade fee is \$125.00 for Municipal. The total cost for all three wells is \$455.00.

Once the department receives these additional fees, processing of the water license can continue. If you have any questions, please call me at 208-762-2800 or email me at eric.davis@idwr.idaho.gov Please respond with in 14 days.

Sincerely,

ERIC DAVIS
Water Resource Agent
Northern Region

Use Typewriter
or
Ball Point Pen

1. DRILLING PERMIT NO. 94 . 94 . N . 0006 . 000

Other IDWR No. 94-07367

2. OWNER:

2. OWNER: ROSE LAKE WATER ASSOCIATION
Name
Address BOX 178
City CATALDO State ID Zip 83810

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.

Twp. 49 North ☒ or South ☐
 Rge. 01 East ☐ or West ☒
 Sec. 28 ^{10 acres} 1/4 NE ^{40 acres} 1/4 SE ^{160 acres} 1/4
 Gov't Lot _____ County Kootenai

Address of Well Site N Doyle Road

(Give at least name of road + Distance to Road or landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. PROPOSED USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other

5. TYPE OF WORK

☒ New Well ☐ Modify or Repair ☐ Replacement ☐ Abandonment

6. DRILL METHOD

☐ Mud Rotary ☒ Air Rotary ☐ Cable ☐ Other

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT	METHOD
Material	From	To	Sacks or Pounds	
Bentonite	0	30	8 sacks	Crumbles

Was drive shoe used? ☒ Y ☐ N

Was drive shoe seal tested? Y ☐ N ☒ How?

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+2	85	250	Steel	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS

☐ Perforations	Method
---------------------------------------	--------

☐ Screens	Screen Type
----------------------------------	-------------

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
						☐	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

_____ 10 ft. below ground Artesian pressure _____ lb.
Depth flow encountered _____ ft. Describe access port or
control devices:

NESE 28 49N 1W

11. WELL TESTS:

☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
30+			1 hr

Water Temp Cold Bottom hole temp

Water Quality test or comments: Clean

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

[illegible]

Completed Depth	200'	(Measurable)
Date: Started	07/11/94	Completed 07/11/94

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name H2O WELL SERVICE INC Firm No. 448

Firm Official John Wheeler Date 7-26-94
and _____

Supervisor or Operator Mark L. Lee Date 7-22-94
(Sign once if Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES