

**WELL LOG AND REPORT TO THE
STATE RECLAMATION ENGINEER OF IDAHO**

027728

RECEIVED	
MAY 11 1954	
Well No.	Department of Reclamation
Permit No.	24429

DO NOT FILL IN

Owner Midvale Cemetery Driller Harold E. Hartling
 Address Midvale, Idaho Address Box 164 Ontario, Ore. Lic. No. 576
 Location of Well: SE 1/4 SW 1/4 Sec. 10, T. 13 N, R. 1 E, W. 2nd County.
 and _____ feet N/S, and _____ feet E/W from _____ corner of _____ 1/4 Sec.
 Water will be used for Irrigation Total depth of well 326
 Size of drilled hole 8" Weight of casing per linear foot National Pipe
 Thickness of casing Standard well casing Casing Material National Pipe
 Diameter, length and location of casing 8" casing 142' 2"
(Casing 12" in diameter and under give inside diameter; casing over 12" in diameter give outside diameter.)
 Number and size of perforations None located _____ feet to _____ feet
 from surface of ground.
 Other Perforations: None
 If flowing well, give flow in c.f.s. _____ or g.p.m. 1 and shut in pressure _____
 If nonflowing well, give depth of standing water from surface _____
 If flowing well, describe control works None
(Type and size of valve, etc.)
 On Bailing test delivery was 2.5 g.p.m. or _____ c.f.s. Drawdown was 112 feet
 Length of time pumped during check was _____ hr. 45 min. Water temp. 42 °Fahrenheit.
 Date of commencement of well Sept 10, 1953 Date of Completion of well Jan 20, 1954
 Type of well rig Keystone, Cable Tool

CASING RECORD

Diam. Casing	From Feet	To Feet	Length	Remarks—Seals, Grouting, Etc.
8"	0	142' 2"		

GENERAL INFORMATION—Pumping Test, Quality of Water, Etc.

see 10713N L R3W

WELL LOG

From Foot	To Foot	Type of Material	Drilling Time		Water-bearing Formation Ass. Yes or No	Casing Perforated Ass. Yes or No
			Hrs.	Min.		
0	4	clay				
4	23	hard green				
23	31	sandy clay (caving)				
31	35	sand				
35	60	clay				
60	108	black mud				
108	118	bits of wood, black mud				
		water went to 40' unable to clear				
		mud out of bottom				
119	128	sand, water-bearing, hard up casing 8'				
128	133	rock ledge				
133	145	shale some sand				
145	162	shale				
162	187	hard shale				
187	198	shale some water				
198	201	hard shale				
201	205	broken shale crust				
205	207	black lava rock				
207	212	broken shale crust				
212	224	Lava rock				
If more space is required use Sheet No. 2						

WELL DRILLERS STATEMENT

This well was drilled under my jurisdiction and the above information is true and correct to the best of my knowledge and belief.

Signed

By

License No.

Dated, 19.....

Subscribed and sworn before me this day of 19.....

Notary Public

Residing at

My Commission expires

Well Driller H. E. Hartling

Well Location Midvale

WELL LOG

[illegible]

13N-3w ————— 10 SEsw