



RECEIVED

NOV 29 2006

DEPARTMENT OF
WATER RESOURCES

November 28, 2006

Idaho Department of Water Resources
The Idaho Water Center
322 E Front St
Boise, ID 83720-0098

Attention: Deborah Gibson

Subject: Proof of Beneficial Use, Mann Farms, Permit No. 63-31298

Dear Deborah,

Enclosed on behalf of Kent Mann of Mann Farms is Proof of Beneficial Use for the above referenced permit. Also enclosed are Well Driller's Reports for wells constructed under this permit and a check for \$100. Please let me know if you have any questions or if we need to supply additional information.

Sincerely,

Scott N. King, P.E.
Senior Project Engineer

cc: Kent Mann

File: 220.0010

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only
Inspected by _____
Twp _____ Rge _____ Sec _____
_____ 1/4 _____ 1/4 _____ 1/4
Lat: : : Long: : :

1. WELL TAG NO. D 25278


1. WELL TAG NO. D 25270
 DRILLING PERMIT NO. 872216 779640
 Other IDWR No. W.R. 63-31298 63-21364

2. OWNER:

2. OWNER: Mann Farms
Name _____
Address 31801 Mann Lane
City Parma State ID Zip 83660

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.



Twp. 6 North XX or South ☐
 Rge. 6 East ☐ or West XX
 Sec. 25 1/4 N/W 1/4 S/E 1/4
 Gov't Lot _____ 10 acres
 County Canyon 40 acres 150 acres
 Lat. : : Long. : :
 Address of Well Site 31801 Mann Ln.
 City Parma

(Give at least name of road + Distance to Road or Landmark)

Lt. Blk. Sub. Name _____

4. USE:

☐ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation stock
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

☐ Air Rotary ☒ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT	METHOD
Material	From	To	Sacks or Pounds	
bentonite chips	0	15	10 sk	poured
bentonite grout	15	38	13 sk	pumped
#10-20 sand	38	94	13,000#	poured

Was drive shoe used? ☐ Y ☐ N Shoe Depth(s) _____
Was drive shoe seal tested? ☐ Y ☐ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
20	0	30	375	steel	☒	☐	☒	☐
14	+2	64	250	steel	☐	☒	☒	☐
					☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS

Perforations _____ Method _____
Screens _____ Screen Type Johnson 304

From	To	Slot Size	Number	Diameter	Material	Casing	Lines
64	94	20		10	stnls	☐	XX
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

13 ft. below ground Artesian pressure _____ lb.
Depth flow encountered _____ ft. Describe access port or
control devices: _____

11. WELL TESTS:

☐ Pump ☐ Bailer ☐ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
3	0		

Water Temp. _____ Bottom hole temp. _____

Water Quality test or comments: _____

Depth first Water Encounter _____

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

[illegible]

RECEIVED

~~SEP 25 2002~~

WATER RESOURCE
WESTERN REGION

13. DRILLER'S CERTIFICATION

We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Stevens & Sons Firm No. 153

Firm Official [Signature] Date 5/3/82

and
Driller or Operator _____ Date _____
(Sign once if you are both Driller and Operator)

FORWARD WHITE COPY TO WATER RESOURCES

11/97
BASIN 63

Talked with Bob Whitney & Terry Scandan concerning well Design!

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT

URCES
DE: 12-402

1. WELL TAG NO. D 10019313
 DRILLING PERMIT NO. 7715-32
 Other IDWR No. _____

2. OWNER:

2. OWNER:
Name M & M Feedlot (Mann Farm)
Address 31801 Mann Lane
City Pazmy State Id Zip 83446

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.


 Twp. 4 North ☒ or South ☐
 Rge. 6 East ☐ or West ☒
 Sec. 25 $\frac{1}{4}$ NW $\frac{1}{4}$ SE $\frac{1}{4}$
 Gov't Lot _____ County Canby
 Lat: _____ Long: _____
 Address of Well Site 31801 Mann Lane
Minn Feedlot City _____
 (Give at least name of road & Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:

☐ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☒ Other Stock

5. TYPE OF WORK check all that apply (Replacement etc.)

☐ New Well ☐ Modify ☐ Abandonment ☒ Other _____

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

7. SEALING PROCEDURES				METHOD
SEAL/FILTER PACK			AMOUNT	
Material	From	To	Sacks or ~~Copper~~	Dry Pour
Bentonite	0	15	5000	
3/16" sea gravel	15	23	2yds	

Was drive shoe used? ☐ Y ☒ N Shoe Depth(s) _____
Was drive shoe seal tested? ☐ Y ☐ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
14"	+2	15	.35		☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe 16' Length of Tailpipe

9. PERFORATIONS/SCREENS

Perforations

Method Johnson Dueschape

Screens

Screen Type

From	To	Slot Size	Number	Diameter	Material	Casing	Line
15	23	050		14"	SS	☒	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

ft. below ground Artesian pressure lb.
Depth flow encountered ft. Describe access port or
control devices: 16" Pipe

11. WELL TESTS:

☒ Pump ☐ Bailer ☐ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
250	10	75	6 hrs

Water Temp. _____ Bottom hole temp. _____

Water Quality test or comments: _____

12. LITHOLOGIC LOG: (Describe repairs or abandonment) Water

[illegible]

13. DRILLER'S CERTIFICATION

19. **STREETS - DEMOLITION**
We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Riverside Inc. Firm No. 333

Firm Official _____ Date _____

and 11/22/01 Date 11-22-01

(Sign only for Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES