

MEMORANDUM


TO: Application for Permit 37-21771 File

FROM: Corey Skinner

DATE: May 16, 2006

SUBJECT: Field Review

On March 14, 2006, Corbin Knowles and I visited the property involved with Application for Permit 37-21771. The following photos document our observations....




ABOVE: View looking northeast across the Snake River towards the property involved with Application for Permit 37-21711 showing the location of the unnamed stream (source) relative to the power house (place of use).

BELOW: View looking across the unnamed stream channel that serves as the source of water for Application for Permit 37-21711.



Photos taken March 14, 2006




ABOVE: View looking down the unnamed stream channel that serves as the source of water for Application for Permit 37-21711.

BELOW: View of diversion to fish pond (and power house penstock below fish pond) on right (north) side of the unnamed stream above the check dam structure. At the time of this photo, 6.88 cfs was flowing over the Cipolletti weir and through this diversion, but note higher water marks on structures.



Photos taken March 14, 2006



ABOVE: View at the downstream end of the fish pond shown in previous views with various points of interest indicated. There was a small amount of water (< 0.5 cfs) flowing over the overflow back to the unnamed stream before spilling

BELOW: View looking down penstock to power house below.



Photos taken March 14, 2006

OVERLAP REVIEW for 37-21771

5/16/2006

P. SKINNER

