

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

765385

Office Use Only			
Inspected by _____			
Twp _____	Rge _____	Sec _____	
1/4 _____		1/4 _____	
Lat: _____	Long: _____		
☒ Air ☐ Flowing Artesian			

1. WELL TAG NO. D 0015318
 DRILLING PERMIT NO. _____
 Other IDWR No. _____

2. OWNER: Developers Diversified Realty
 Name _____
 Address 455 E 500 S. Suite 400
 City Salt Lake City State UT Zip 84111

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.

N		E		S		W	
X							

Twp. 3 North ☒ or South ☐
 Rge. 1 East ☒ or West ☐
 Sec. 9 NE 1/4 NW 1/4
 Gov't Lgt. _____ County 000 160 acres
 Lat: _____ Long: _____
 Address of Well Site Records Drive
 City Meridian

(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Bk. _____ Sub. Name _____

4. USE:
☐ Domestic ☐ Municipal ☐ Monitor ☒ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD
☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT		METHOD
Material	From	To	Sacks or Pounds		
<u>Bentonite</u>	<u>0</u>	<u>20</u>	<u>850#</u>		<u>overbore</u>

Was drive shoe used? ☒ N Shoe Depth(s) 92
 Was drive shoe seal tested? ☒ Y ☐ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
<u>8"</u>	<u>12</u>	<u>92</u>	<u>250</u>	<u>Steel</u>	☒	☐	☒	☐

Length of Headpipe 10 Length of Tailpipe _____

9. PERFORATIONS/SCREENS

Perforations _____ Method _____
 Screens _____ Screen Type Nagaska - pipe

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
<u>94</u>	<u>114</u>	<u>230</u>		<u>6"</u>	<u>SS</u>	☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

18 ft. below ground Artesian pressure _____ lb.
 Depth flow encountered _____ ft. Describe access port or control devices: well cap

11. WELL TESTS:

Yield gal./min.	Drawdown	Pumping Level	Time
<u>200</u>			<u>9 hours</u>

Water Temp. _____ Bottom hole temp. _____

Water Quality test or comments: _____

Depth first Water Encounter 20

12. LITHOLOGIC LOG: (Describe repairs or abandonment) Water

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
<u>12</u>	<u>0</u>	<u>12</u>	<u>pit run - rocks & sand</u>		
<u>4</u>	<u>12</u>	<u>20</u>	<u>cobble stone & sand</u>		
<u>8</u>	<u>20</u>	<u>22</u>	<u>cobble stone & sand</u>	☒	
	<u>22</u>	<u>32</u>	<u>gravel & clay</u>	☒	
	<u>32</u>	<u>35</u>	<u>clay</u>		
	<u>35</u>	<u>45</u>	<u>soft sandy clay</u>	☒	
	<u>45</u>	<u>55</u>	<u>sand w/ some gravel rocks</u>	☒	
	<u>55</u>	<u>82</u>	<u>sand (slight brassy color)</u>	☒	
	<u>82</u>	<u>92</u>	<u>sand w/ thin clay pieces</u>		
			<u>then straight clay</u>		
	<u>92</u>	<u>93</u>	<u>sand</u>		
	<u>93</u>	<u>96</u>	<u>clay</u>		
	<u>96</u>	<u>100</u>	<u>sand</u>		
	<u>100</u>	<u>117</u>	<u>sand</u>	☒	
				☒	

RECEIVED

AUG 02 2000

WATER RESOURCES
WESTERN REGION

RECEIVED

AUG 15 2000

Department of Water Resources

Completed _____ Depth 114 (Measurable)
 Date: Started 7-17-00 Completed 7-19-00

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Adams Pump & Drill No. 0457

Firm Official Dave Adams Date 7-27-00

and Driller or Operator Dave Adams Date 7-27-00

(Sign once if Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES