RECEIVED

JUL 12 2004

WATER RESOURCES
WESTERN REGION

804514

Office Use Only
Inspected by ____
Twp ____ Rge ____ Sec ____
____ 1/4 ____ 1/4 ____ 1/4
Lat: Long:

Form 238-7
3/95-C96

# IDAHO DEPARTMENT OF WATER RESOURCES
# WELL DRILLER'S REPORT

**1. DRILLING PERMIT NO.** D 0020551
Other IDWR No. «Other IDWR No» 07-1414133

**2. OWNER:**
Name Marc Agostini
Address 29407 Bluewater Rd.
City Malibu State CA Zip 90265

**3. LOCATION OF WELL by legal description:**
Sketch map location must agree with written location

N

W E

S

Twp 10 North ☒ or South ☐
Rge 4 East ☐ or West ☒
Sec 11 «QQQ» 10 acres SE 1/4 40 acres NE 1/4 160 acres

Gov't lot ____ County Washington

Lat: : : Long: : :

Address of Well Site 2301 Cove Rd.
City Weiser
(Give at least name of road + Distance to Road or Landmark)

Lt. «Lt» Blk. «Blk» Sub. Name «Subname»

**4. USE:**
☐ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☒ Other Wild Life

**5. TYPE OF WORK** check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other ____

**6. DRILL METHOD**
☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other ____

**7. SEALING PROCEDURES**

| SEAL/FILTER PACK | | | AMOUNT | METHOD |
|---|---|---|---|---|
| Material | From | To | Sacks or Pounds | |
| Bentonite | 0 | 18 | 200lbs | Pour |
| | | | | |
| | | | | |

Was drive shoe used? ☐ Y ☒ N Shoe Depth(s) ____
Was drive shoe seal tested? ☐ Y ☒ N How? ____

**8. CASING/LINER:**

| Diameter | From | To | Gauge | Material | Casing | Liner | Welded | Threaded |
|---|---|---|---|---|---|---|---|---|
| 14 | +2 | 20 | .250 | steel | ☒ | ☐ | ☒ | ☐ |
| | | | | | ☐ | ☐ | ☐ | ☐ |
| | | | | | ☐ | ☐ | ☐ | ☐ |

Length of Headpipe ____ Length of Tailpipe ____

**9. PERFORATIONS/SCREENS**
☐ Perforations Method ____
☐ Screens Screen Type ____

| From | To | Slot Size | Number | Diameter | Material | Casing | Liner |
|---|---|---|---|---|---|---|---|
| | | | | | | ☐ | ☐ |
| | | | | | | ☐ | ☐ |
| | | | | | | ☐ | ☐ |

**10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:**
0 ft. below ground Artesian Pressure 3 lb
Depth flow encountered 116 ft. Describe access port or control devices: cap

**11. WELL TESTS:**
☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

| Yield gal/min. | Drawdown | Pumping Level | Time |
|---|---|---|---|
| 600 | 120 | 120 | 5hr |
| | | | |
| | | | |

Water Temp. 56 Bottom hole temp. 56
Water Quality test or comments: ____
Depth first Water Encountered 116

**12. LITHOLOGIC LOG: (Describe repairs or abandonment)**

| Bore Dia | From | To | Remarks: Lithology, Water Quality & Temp. | Water Y | Water N |
|---|---|---|---|---|---|
| 20 | 0 | 1 | Top Soil | | X |
| 20 | 1 | 18 | Brown Clay | | X |
| 14 | 18 | 110 | Blue Clay | | X |
| 14 | 110 | 116 | Broken Sand Stone | X | |
| 14 | 116 | 130 | Blue Clay | | X |
| 14 | 130 | 133 | Sand Stone | X | |
| 14 | 133 | 200 | Blue Clay | | X |
| 14 | 200 | 210 | Hard Blue Clay | | X |

Completed Depth: 210 (Measurable)
Date: Started 6/29/04 Completed 7/6/04

**13. DRILLER'S CERTIFICATION**
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name Treasure Valley Drilling Firm No. 560
Firm Official ____ Date 7/7/04
Supervisor or Operator ____ Date 7/7/04
(Sign once if Firm Official & Operator)

Date: 7/7/2004 Time: 12:34 PM