Form 238-7
6/95

DMD

IDAHO L[illegible]PARTMENT OF WATER RESOUF[illegible]S

WELL DRILLER'S REPORT

Use Typewriter or Ballpoint Pen

065976

Office Use Only
Inspected by _____
Twp____ Rge____ Sec____
____1/4____1/4____1/4
Lat: : : Long: : :

1. DRILLING PERMIT NO. 23-97-E-024-000
Other IDWR No. Tag # D0004177

2. OWNER:
Name Hoffman Summer Homes Area
Address % USDA 2215 Highland Dr.
City Blackfoot State ID Zip 83221

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

N / W / E / S

Twp. 3 North ☐ or South ☒
Rge. 46 East ☒ or West ☐
Sec. 8 NW 1/4 (10 acres) NW 1/4 (40 acres) ____ 1/4 (160 acres)
Gov't Lot ____ County Bonneville
Lat: : : Long: : :
Address of Well Site _____
City _____
(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD
☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
Bentonite	0	24'	40 bags	overbore

Was drive shoe used? ☐ Y ☒ N Shoe Depth(s) _____
Was drive shoe seal tested? ☐ Y ☐ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+1½'	18½'	.280	Steel	☒	☐	☐	☐
4"	14'	24'	SCH40	PVC	☒	☐	☐	☒
4"	44'	64'	SCH40	PVC	☒	☐	☐	☒
4"	244'	274'	SCH40	PVC	☒	☐	☐	☒

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS
☐ Perforations Method _____
☐ Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
24'	44'	.020		4"	PVC	☒	☐
64'	244'	.020		4"	PVC	☒	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
108 ft. below ground Artesian pressure _____ lb.
Depth flow encountered _____ ft. Describe access port or control devices: _____

11. WELL TESTS:
☐ Pump ☐ Bailer ☐ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time

Water Temp. _____ Bottom hole temp. ____
Water Quality test or comments: _____
Depth first Water Encountered ____

12. LITHOLOGIC LOG: (Describe repairs or abandonment) Wa

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y
10"	0	2'	DIRT	
10"	2'	5'	Rock	
10"	5'	12'	DIRT	
10"	12'	18'	Clay	
10"	18'	38'	Gravel, DIRT, & Clay	
8"	38'	118'	Brown Clay	
8"	118'	142'	Green Shale	✓
8"	142'	200'	Brown Clay	
8"	200'	204'	Blue Clay	
8"	204'	274'	Sandstone Shale	✓

RECEIVED
RECEIVED OCT 0 1 1997
OCT 0 8 1997 Department of Water Resources Eastern Region
Department of Water Resources

Completed Depth 274 Ft. (Measurat
Date: Started 9/16/97 Completed 9/20/97

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied w the time the rig was removed.

Firm Name Vollmer Well Drilling Firm No. 3
Firm Official _____ Date 09/2
and
Supervisor or Operator _____ Date 09/29
(Signature if Firm Official & Operator)

Receipt E023632
$200.00

FORWARD WHITE COPY TO WATER RESOURCES