

Comment Report

23-7068

1. dcarlson 7/9/2003 Field Report Narrative

Comment: dam in unnamed stream with a 6" pvc pipeline to power plant to YMCA camp. 7.5KW lima electrical
condec mac alternator. 250 foot drop 1520 feet length of pipe to power plant

2. kwalker 6/8/2004 Call up date for review

Comment: In review of this proposed license, I find that proof of b/u was made in 1989. Normally we allow 10 years after proof has been submitted for call up date for review. However, since we did not get this licensed within 10 years of proof I recommend we allow until 10/3/2009 for call up review date.