

Formation Spring Labeled "two"
current metered on 7/20/2011 at
3.25 cfs flow plus 1 cfs flow
approximated leaking through
bypass pipes to the N. of this
diversion. (possibly Panting ditch)



A photograph of a small, shallow stream or diversion channel. The water is dark and still, reflecting the surrounding greenery. On the left bank, there is a small, weathered wooden structure, possibly a headgate or a small bridge. The right bank is covered in dense, bright green vegetation, including tall grasses and yellow wildflowers. The background is filled with more trees and foliage, creating a lush, natural setting.

Margaret Panting Diversion @
Formation Springs 7/25/2011
Current metered flow 2.93 CFS 15'
downstream from headgate directed
on site by Mike Panting



North diversion of Formation Spring
labeled "One" current metered at
9.09 cfs flow on 7/20/2011 (possibly
the Clark Brown portion)

A photograph of a wooden diversion headgate structure, partially obscured by dense green foliage and trees. The structure appears to be made of weathered wood and has a circular component at the top. The scene is lush with green leaves and branches, with some bare, thin branches hanging down from the top left. In the foreground, there are some tall, thin grasses or reeds.

Clark Brown diversion headgate
Current metered @ 4.4 CFS on
7/25/2011 aprox. 25' downstream
Directed on site by Mike Panting