

RECEIVED

Form 808-7 7 1998
11/97IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

78222

Office Use Only			
Inspected by			
Twp	Rge	Sec	
1/4	1/4	1/4	
Lat: : :	Long: : :		

NORTHERN REGION

1. WELL ID NO. D 0003796

DRILLING PERMIT NO. 97-98417

Other IDWR No. _____

2. OWNER:

Name Ralph & Rita HuddlestonAddress 4000-76th Street NE #50City Marysville State WA Zip 98270

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.

N		Twp. <u>57</u>		North ☒ or South ☐	
W		Rge. <u>05</u>		East ☐ or West ☒	
E		Sec. <u>17</u>		1/4 <u>NW</u> 1/4 <u>SW</u> 1/4	
S		Gov't Lot _____		County <u>Bonner</u>	
		Lat: : :		Long: : :	
		Address of Well Site <u>Bear Paw Road</u>		City <u>Priest River</u>	

(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:

- ☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK	From	To	AMOUNT	METHOD
Material			Sacks or Pounds	
<u>Bentonite</u>	<u>0</u>	<u>19</u>	<u>6sacks</u>	<u>Overbore</u>

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) _____
Was drive shoe seal tested? ☐ Y ☐ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
<u>6"</u>	<u>+1</u>	<u>229</u>	<u>250</u>	<u>steel</u>	☒	☐	☒	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS

Perforations _____ Method _____
Screens _____ Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

80 ft. below ground Artesian pressure _____ lb.Depth flow encountered 80 ft. Describe access port or control devices: welded well cap57N 5W 17

11. WELL TESTS:

☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal/min.	Drawdown	Pumping Level	Time
<u>22gpm</u>		<u>275'</u>	<u>1 hr.</u>

Water Temp. 49F

Bottom hole temp. _____

Water Quality test or comments: clearDepth first Water Encounter 80'

12. LITHOLOGIC LOG: (Describe repairs or abandonment) Water

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
10	0	3	Topsoil		X
10	3	19	Clay/brn		X
6	19	24	Clay/brn		X
6	24	56	Clay w/fine sand lenses		X
6	56	103	Clay/gray w/fine sand lenses	X	
6	103	190	Fine sand-gray w/gravel		X
6	190	225	Decomposed granite		X
6	225	240	Granite/brn&white/soft		X
6	240	244	Granite/brn&white/frac		
			@ 10gpm	X	
6	244	264	Granite/brn&white/soft		X
6	264	275	Granite/brn&white/frac		
			@ 12gpm	X	

Completed Depth 275' (Measurable)
Date: Started 6-12-98 Completed 6-14-98

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Intermountain Drilg. Firm No. 513Firm Official [Signature] Date 6-15-98and Driller or Operator [Signature] Date 6-15-98

(Sign once if Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES

SCANNED

MAR 21 2024

Identify

Identify from:

Bonner Parcels 2007

Bonner Parcels 2007

Location:

2,277,480.203 1,902,633.887 Meters

Field	Value
FID	16127
Shape	Polygon
UPDATED	03/14/2003
PIN	RP57N05W175571A
OWNER	HUDDLESTON, RALPH A & RITA M
ADDRESS1	2064 BEAR PAW RD
ADDRESS2	
CITY	PRIEST RIVER
STATE	ID
ZIPCODE	83856
P_ADDRESS	2064 BEAR PAW RD
P_ZIPCODE	83856
SUB_NAME	
LEGAL1	
LEGAL2	
LEGAL3	
LEGAL4	
LEGAL5	
LEGAL6	
YEAR_BUILT	1999
ACRES	19.6
SOURCETHM	Bonner.shp
AREA_METER	79481.992
PERIMETER_	1372.718

Identified 1 feature

SCANNED

MAR 21 2024