97-9064

RECEIVED
JUN 11 1996
IDWR

Form 238-7
3/95

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Use Typewriter or Ballpoint Pen 097444

Office Use Only
Inspected by _____
Twp____ Rge____ Sec____
____1/4 ____1/4 ____1/4
Lat: : : Long: : :

1. ~~DRILLING PERMIT NO.~~ 97 - 96 - N - 0025 - ____
Other IDWR No. _____

2. OWNER:
Name Melvin and Wilma George
Address HC06 Box 125
City Priest River, State ID Zip 83856

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

N / W / E / S — x

Twp. 56 North ☒ or South ☐
Rge. 04 East ☐ or West ☒
Sec. 08, ____ 1/4 (10 acres) SE 1/4 (40 acres) NW 1/4 (160 acres)
Gov't Lot ____ County Bonner
Lat: : : Long: : :
Address of Well Site Wesley Lane off Eastside Road City Priest River
(Give at least name of road + Distance to Road or Landmark)
Lt. 03 Blk. _____ Sub. Name Wesley Sub.

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD
☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
Bentonite	0	19	3sacks	Overbore

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) _____
Was drive shoe seal tested? ☐ Y ☒ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+1	170	250	steel	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS
☐ Perforations Method _____
☒ Screens Screen Type Cook/telescoping

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
167	172	16		6"	stainless	☐	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
120 ft. below ground Artesian pressure _____ lb.
Depth flow encountered 120 ft. Describe access port or control devices: _____

SENW 8 56N 4W

11. WELL TESTS:
☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
6-7		172'	1 hr.

Water Temp. 49F Bottom hole temp. _____
Water Quality test or comments: clear
Depth first Water Encountered 120'

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
8	0	19	Sand & gravel		x
6	19	34	Sand & gravel		x
6	34	170	Clay w/fine sand lenses	x	
6	170	172	Sand & gravel	x	

Completed Depth 172' (Measurable)
Date: Started 6-5-96 Completed 6-6-96

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name Intermountain Drilling Firm No. 0513
Firm Official _____ Date 6-7-96
and
Supervisor or Operator same Date _____
(Sign once if Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES