

IDAHO DEPARTMENT OF WATER RESOURCES WELL DRILLER'S REPORT

Office Use Only			
Well ID No.			
Inspected by			
Twp	Rge	Sec	
1/4	1/4	1/4	
Lat:	:	Long:	:

1. WELL TAG NO. D 0028156
 DRILLING PERMIT NO. 791060
 Water Right or Injection Well No. _____

2. OWNER:
 Name Cheryl Bowers
 Address Acme Given
 City Coolin State ID Zip 83821



3. LOCATION OF WELL by legal description:
 You must provide address or Lot, Blk, Sub. or Directions to well.
 Twp. 59 North ☒ or South ☐
 Rge. 4 East ☐ or West ☒
 Sec. 10 1/4 NE 1/4 NE 1/4
 Gov't Lot _____ County Bonner
 Lat: _____ Long: _____
 Address of Well Site Turn behind Coolin store
4 block back City Coolin
 (Give at least name of road + Distance to Road or Landmark)
 Lt. _____ Blk. _____ Sub. Name _____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD:
☐ Air Rotary ☒ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

Seal Material	From	To	Weight / Volume	Seal Placement Method
<u>Bentonite</u>	<u>0</u>	<u>18</u>	<u>250 lbs</u>	<u>Temp Casing</u>

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 123'
 Was drive shoe seal tested? ☐ Y ☒ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
<u>6"</u>	<u>+1</u>	<u>123</u>	<u>250</u>	<u>Steel</u>	☒	☐	☒	☐

Length of Headpipe _____ Length of Tailpipe _____
 Packer ☒ Y ☐ N Type R-packer

9. PERFORATIONS/SCREENS PACKER TYPE

Perforation Method _____

Screen Type & Method of Installation Johnson - pull back

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
<u>123</u>	<u>128</u>	<u>25</u>		<u>6"</u>	<u>SS</u>	☐	☐

10. FILTER PACK

Filter Material	From	To	Weight / Volume	Placement Method

11. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
100' ft. below ground Artesian pressure _____ lb.
 Depth flow encountered _____ ft. Describe access port or control devices: _____

12. WELL TESTS:

☐ Pump	☒ Bailer	☐ Air	☐ Flowing Artesian
Yield gal./min.	Drawdown	Pumping Level	Time
<u>8+</u>	<u>2'</u>	<u>102'</u>	<u>1hr</u>

Water Temp. 60.5 Bottom hole temp. _____

Water Quality test or comments: _____

Depth first Water Encounter 110'

13. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water
<u>8"</u>	<u>0</u>	<u>18</u>	<u>TOP Soil. sand</u>	☒ Y ☒ N
<u>6"</u>	<u>18</u>	<u>60</u>	<u>Sand</u>	☒ Y ☒ N
<u>6"</u>	<u>60</u>	<u>110</u>	<u>Sand</u>	☒ Y ☒ N
<u>6"</u>	<u>110</u>	<u>128</u>	<u>Sand</u>	☒ Y ☒ N

RECEIVED

APR 03 2003

IDWR North

Completed Depth 128' (Measurable)
 Date: Started 1/29/03 Completed 2/5/03

14. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Cop/Ring & Sons Firm No. 148

Principal Driller Steve Pettis Date 2/25/03

Driller or Operator II _____ Date _____

Operator I _____ Date _____

Principal Driller and Rig Operator Required.
 Operator I must have signature of Driller/Operator II.

59N 4W 10

FORWARD WHITE COPY TO WATER RESOURCES