RECEIVED
OCT 05 2000
IDWR/North

11/6/00

Form 238-7
11/97

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only
Inspected by _____
Twp ____ Rge ____ Sec ____
____ 1/4 ____ 1/4 ____ 1/4
Lat: : : Long: : :

1. WELL TAG NO. D 136533
DRILLING PERMIT NO. - - - -
Other IDWR No. 76147

2. OWNER:
Name BEN DAVIS
Address 72 ETTLL MEADOWS DR.
City PRIEST RIVER State ID Zip 83856

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

Twp. 57 North ☑ or South ☐
Rge. 4 East ☐ or West ☑
Sec. 20, NW 1/4 SW 1/4 ____ 1/4 (10 acres, 40 acres, 160 acres)
Gov't Lot ____ County BONNER
Lat: : : Long: : :
Address of Well Site 4-3 N. ON PENINSULA RD. SE. 3M. P. LOOP RD City PRIEST RIVER
(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:
☑ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)
☑ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD
☐ Air Rotary ☑ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
BENTONITE	0	18	200 LB	TEMP CASE

Was drive shoe used? ☑ Y ☐ N Shoe Depth(s) 22
Was drive shoe seal tested? ☐ Y ☑ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	+1.5	22	.250	STEEL	☑	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe 1.5' Length of Tailpipe .5'

9. PERFORATIONS/SCREENS
Perforations Method DROP SCREEN - PULL CASE
Screens Screen Type STAINLESS - TELESCOPE

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
22	27	10		5½	SS	☐	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
12 ft. below ground Artesian pressure _____ lb.
Depth flow encountered _____ ft. Describe access port or control devices: PITLESS CAP

57N 4W 20

11. WELL TESTS:
☐ Pump ☑ Bailer ☐ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
5	9	21	2 HRS

Water Temp. _____ Bottom hole temp. _____
Water Quality test or comments: _____
Depth first Water Encounter 12'

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
8	0	6	BROWN CLAY		✓
8	6	18	BROWN CLAY SAND 13'	✓	
6	18	21	BROWN CLAY SAND	✓	
6	21	27	GRAY CLAY SAND	✓	
6	27	32	GRAY CLAY		✓

Completed Depth 32 (Measurable)
Date: Started 8/18/00 Completed 8/25/00

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were compiled with at the time the rig was removed.

Company Name WOOD WELL DRILLING Firm No. 389
Firm Official Phillip Wood Date 10/3/00
and
Driller or Operator _____ Date _____
(Sign once if Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES