Form 238-7
6/07

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

1. WELL TAG NO. D D0067711
Drilling Permit No. 872839
Water right or injection well #

2. OWNER: Charles Manning
Name Linda Cashman
Address 2132 Wisconsin N.
City Albuquerque State NM Zip 87110

3.WELL LOCATION:
Twp. 56 North ☒ or South ☐ Rge. 04 East ☐ or West ☒
Sec. 36 ____ 10 acres ____ 1/4 SW 40 acres 1/4 NW 160 acres 1/4
Gov't Lot ____ County Bonner
Lat. 48 ° 09: 644 (Deg. and Decimal minutes)
Long. 116 ° 47: 091 (Deg. and Decimal minutes)
Address of Well Site 13073 Hwy 2
City Laclede
(Give at least name of road + Distance to Road or Landmark)
Lot. ____ Blk. ____ Sub. Name

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation ☐ Thermal ☐ Injection
☐ Other

5. TYPE OF WORK:
☒ New well ☐ Replacement well ☐ Modify existing well
☐ Abandonment ☐ Other

6. DRILL METHOD:
☒ Air Rotary ☐ Mud Rotary ☐ Cable ☐ Other

7. SEALING PROCEDURES:

Seal material	From (ft)	To (ft)	Quantity (lbs or ft³)	Placement method/procedure
Bentonite	0	14	400 lbs.	Dry Pour
Hole Plug	14	38	600 lbs.	Dry Pour

8. CASING/LINER:

Diameter (nominal)	From (ft)	To (ft)	Gauge/ Schedule	Material	Casing	Liner	Threaded	Welded
6"	+2	45	.250	Steel	☒	☐	☐	☒
4"	-7	145	.200	PVC	☐	☒	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 45

9. PERFORATIONS/SCREENS:
Perforations ☒ Y ☐ N Method Skilsaw
Manufactured screen ☐ Y ☒ N Type
Method of installation

From (ft)	To (ft)	Slot size	Number/ft	Diameter (nominal)	Material	Gauge or Schedule
125	145	1/8x6	48	4"	PVC	.200

Length of Headpipe ____ Length of Tailpipe
Packer ☐ Y ☒ N Type

10.FILTER PACK:

Filter Material	From (ft)	To (ft)	Quantity (lbs or ft³)	Placement method

11. FLOWING ARTESIAN:
Flowing Artesian? ☐ Y ☒ N Artesian Pressure (PSIG)
Describe control device

12. STATIC WATER LEVEL and WELL TESTS:
Depth first water encountered (ft) 35 Static water level (ft) 35
Water temp. (°F) Cold Bottom hole temp. (°F) Cold
Describe access port Welded Steel Cap

Well test:

Drawdown (feet)	Discharge or yield (gpm)	Test duration (minutes)
140	20	1 hr.

Test method:

Pump	Bailer	Air	Flowing artesian
☐	☐	☒	☐
☐	☐	☐	☐

Water quality test or comments: Clear

13. LITHOLOGIC LOG and/or repairs or abandonment:

Bore Dia. (in)	From (ft)	To (ft)	Remarks, lithology or description of repairs or abandonment, water temp.	Water Y	Water N
10	0	35	Brown Clay & Sand		X
10	35	38	Decomposed Granite (trickle h2o)	X	
8	38	45	Broken Granite		X
6	45	108	Soft Granite		X
6	108	112	Fractured Granite	X	
6	112	121	Hard Granite		X
6	121	145	Soft Granite		X

RECEIVED
AUG 0 8 2014
IDWR / NORTH

Completed Depth (Measurable): 145
Date Started: Aug 1, 2014 Date Completed: Aug 4, 2014

14. DRILLER'S CERTIFICATION:
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name H2O Well Service Inc. Co. No. 448
*Principal Driller [signature] Date Aug 5, 2014
*Driller [signature] Date 8-5-14
*Operator II Date
Operator I Date

*** Signature of Principal Driller and rig operator are required.**