

IDAHO DEPARTMENT OF WATER RESOURCES WELL DRILLER'S REPORT

Office Use Only			
Well ID No. _____			
Inspected by _____			
Twp _____	Rge _____	Sec _____	
1/4 _____	1/4 _____	1/4 _____	
Lat: _____	Long: _____		

1. WELL TAG NO. D 0040910
 DRILLING PERMIT NO. 36641
 Water Right or Injection Well No. _____

2. OWNER:
 Name Monte Wesbitt
 Address E 174th Fourth Ave
 City Spokane Valley State WA Zip 99016

3. LOCATION OF WELL by legal description:
 You must provide address or Lot, Blk, Sub. or Directions to well.
 Twp. 59 North ☒ or South ☐
 Rge. 4 East ☐ or West ☒
 Sec. 10 1/4 SW 1/4 NE 1/4
 Gov't Lot _____ County Bonne
 Lat: _____ Long: _____
 Address of Well Site Behind Berlin Carwash City Certina
 (Give at least name of road - Distance to Road or Landmark)
 Lt. _____ Blk. _____ Sub. Name _____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD:
☐ Air Rotary ☒ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

Seal Material	From	To	Weight/Volume	Seal Placement Method
<u>Bentite</u>	<u>0</u>	<u>18</u>	<u>250lbs</u>	<u>Temp Casing</u>

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 115'
 Was drive shoe seal tested? ☐ Y ☒ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
<u>6 + 1</u>	<u>115</u>	<u>20</u>	<u>20</u>	<u>Steel</u>	☒	☐	☒	☐

Length of Headpipe _____ Length of Tailpipe _____
 Packer ☒ Y ☐ N Type K

9. PERFORATIONS/SCREENS PACKER TYPE

Perforation Method Inc Screen

Screen Type & Method of Installation _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
<u>115</u>	<u>120</u>	<u>PS</u>	<u>304</u>	<u>6"</u>	<u>SS</u>	☐	☐

10. FILTER PACK

Filter Material	From	To	Weight / Volume	Placement Method

11. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
100 ft. below ground Artesian pressure _____ lb.
 Depth flow encountered _____ ft. Describe access port or control devices: _____

12. WELL TESTS:

Yield gal./min.	Drawdown	Pumping Level	Time
<u>10</u>	<u>5</u>	<u>105</u>	<u>1 hr</u>

Water Temp. COLD Bottom hole temp. _____
 Water Quality test or comments: _____

13. LITHOLOGIC LOG: (Describe repairs or abandonment) Water _____

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
<u>8</u>	<u>0</u>	<u>18</u>	<u>sand cobbles, Boulders</u>	☒	☐
<u>6</u>	<u>18</u>	<u>40</u>	<u>sand, clay</u>	☒	☐
<u>6</u>	<u>40</u>	<u>83</u>	<u>fine sand</u>	☒	☐
<u>6</u>	<u>83</u>	<u>100</u>	<u>med. sand</u>	☒	☐
<u>6</u>	<u>100</u>	<u>120</u>	<u>med. fine, sand</u>	☒	☐

RECEIVED
 AUG 04 2006
 IDWR/North

RECEIVED
 JUN 20 2006
 IDWR/North

RECEIVED
 MAY 25 2006
 IDWR/North

Completed Depth 120' (Measurable)
 Date: Started 10-11-05 Completed 11-10-05

14. DRILLER'S CERTIFICATION
 I/We certify that all minimum well construction standards were complied with at the time the rig was removed.
 Company Name Chas Pittman Sons Firm No. 1108
 Principal Driller Steve Pittman Date 11-10-05
 and Driller or Operator II Joe Ockert Date 11-10-05
 Operator I _____ Date _____

Principal Driller and Rig Operator Required.
 Operator I must have signature of Driller/Operator II.

59N 4W 10