

WELL DRILLER'S REPORT

CORRECTED REPORT

1. WELL TAG NO. D 06511603
DRILLING PERMIT NO. 815440
Water Right or Injection Well No. _____

2. OWNER:
Name Deatrice Moore
Address P.O. Box 1597
City Priest River State ID Zip 83856

3. LOCATION OF WELL by legal description:
You must provide address or Lot, Blk, Sub. or Directions to well.
Twp. 57 North ☒ or South ☐
Rge. 5 East ☐ or West ☒
Sec. 24 1/4 NW 1/4 SW 1/4
Gov't Lot _____
County Bonner
Lat: _____ Long: _____
Address of Well Site Carey Spur Rd. City Priest River
(Give at least name of road + Distance to Road or Landmark)
Lt. _____ Blk. _____ Sub. Name _____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD:
☒ Air Rotary ☒ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

Seal Material	From	To	Weight / Volume	Seal Placement Method
<u>Bentonite</u>	<u>0</u>	<u>20</u>	<u>400lbs</u>	<u>Overbore</u>

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 300'
Was drive shoe seal tested? ☐ Y ☒ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
<u>6</u>	<u>+1</u>	<u>300</u>	<u>280</u>	<u>Steel</u>	☒	☐	☒	☐

Length of Headpipe _____ Length of Tailpipe _____
Packer ☒ Y ☐ N Type IC

9. PERFORATIONS/SCREENS PACKER TYPE

From	To	Slot Size	Number	Diameter	Material	Screen	Liner
<u>300</u>	<u>305</u>	<u>30</u>	<u>3x1</u>	<u>6"</u>	<u>SS</u>	☒	☐

10. FILTER PACK

Filter Material	From	To	Weight / Volume	Placement Method

11. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

220' ft. below ground Artesian pressure _____ lb.
Depth flow encountered _____ ft. Describe access port or control devices: _____

57N SW 24

Office Use Only			
Well ID No.			
Inspected by			
Twp	Rge	Sec	
1/4	1/4	1/4	
Lat:	:	Long:	:

12. WELL TESTS:

Yield gal./min.	Drawdown	Pumping Level	Time
<u>10+</u>	<u>10'</u>	<u>230</u>	<u>1hr</u>

Water Temp. COLD Bottom hole temp. _____
Water Quality test or comments: _____

13. LITHOLOGIC LOG: (Describe repairs or abandonment) Water

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
<u>8</u>	<u>0</u>	<u>20</u>	<u>Silt,</u>		☒
<u>6</u>	<u>20</u>	<u>80</u>	<u>Silt, clay</u>		☒
<u>6</u>	<u>80</u>	<u>160</u>	<u>Silt, clay</u>		☒
<u>6</u>	<u>160</u>	<u>275</u>	<u>Silt, clay</u>		☒
<u>6</u>	<u>275</u>	<u>295</u>	<u>Sand, clay</u>	☒	
<u>6</u>	<u>295</u>	<u>305</u>	<u>Sand</u>	☒	

RECEIVED
FEB 22 2007
IDWR/North
RECEIVED
FEB 16 2007
IDWR/North

Completed Depth 305' (Measurable)
Date: Started 1/23/07 Completed 1/31/07

14. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.
Company Name Carey Potts & Sons Firm No. 148
Principal Driller Steve Potts Date 2/1/07
and
Driller or Operator II John E. Potts Date 2/1/07
Operator I _____ Date _____

Principal Driller and Rig Operator Required.
Operator I must have signature of Driller/Operator II.