Form 238-7
11/97

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only
Inspected by _____
Twp ____ Rge ____ Sec ____
____ 1/4 ____ 1/4 ____ 1/4
Lat: : : Long: : :

1. WELL TAG NO. D ~~D0013636~~
DRILLING PERMIT NO. - - - -
Other IDWR No. 766575

POSTED

2. OWNER:
Name Ernest Lasley
Address 403 Sandborn Creek Rd.
City Priest River State ID Zip 83822

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

N / W / E / S

Twp. 56 North ☒ or South ☐
Rge. 4 East ☐ or West ☒
Sec. 7, ____ 1/4 (10 acres) NE 1/4 (40 acres) SE 1/4 (160 acres)
Gov't Lot ____ County Bonner
Lat: : : Long: : :
Address of Well Site 403 Sandborn Rd.
City Priest River
(Give at least name of road + Distance to Road or Landmark)

Lt. ____ Blk. ____ Sub. Name ____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other ____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other ____

6. DRILL METHOD
☐ Air Rotary ☒ Cable ☐ Mud Rotary ☐ Other ____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
Bentonite	0	18	6	Temp casing

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 85 ft.
Was drive shoe seal tested? ☐ Y ☒ N How? ____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	+1	85	.250	Steel	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe ____ Length of Tailpipe ____

9. PERFORATIONS/SCREENS
Perforations Method Pull back
Screens Screen Type Telescoping

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
85	95	6		6	SS	☐	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
60 ft. below ground Artesian pressure ____ lb.
Depth flow encountered ____ ft. Describe access port or control devices: ____

56N 4W 7

11. WELL TESTS:
☐ Pump ☒ Bailer ☐ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
10	20	80	1 hr.

Water Temp. cold Bottom hole temp. ____
Water Quality test or comments: ____
Depth first Water Encounter 65 ft.

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
8	0	20	Top soil, sand gravel		x
6	21	30	sand fine		x
6	31	50	sand fine		x
6	51	64	sand fine		x
6	65	95	sand fine	x	
6	95	98	clay, fine sand	x	

RECEIVED
OCT 10 2000
IDWR/North

Completed Depth 95 ft. (Measurable)
Date: Started 9-11-00 Completed 9-18-00

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Carl Pitts & Sons drilling Firm No. 168
Firm Official Carl Pitts Date 9-18-00
and
Driller or Operator Steve Pitts Date 9-18-00
(Sign once if Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES