Form 238-7
11/97

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

OFFICE USE ONLY
Inspected by
Twp. ____ Rge. ____ Sec ____
____ 1/4 ____ 1/4 ____ 1/4
Lat. : : Long : :

1. WELL TAG NO. D 0054615
DRILLING PERMIT NO. 852532
Other IDWR No.

2. OWNER
Name RICHARD & KATHY GALBREATH
Address 1391 TANGLEWOOD DRIVE
City PRIEST RIVER State ID Zip 83856

3. LOCATION OF WELL by legal description
Sketch map location must agree with written location.

N / W / E / S

Twp. 58 North (●) or South ( )
Rge. 4 East ( ) or West (●)
Sec. 17 ____ 1/4 (10 acres) NE 1/4 (40 acres) SW 1/4 (160 acres)
Gov't Lot ____ County
Lat. : :
Long : :

Address of Well
1391 TANGLEWOOD DRIVE City Priest River
(Give at least name of road + Distance to Road or Landmark)

Lt. ____ Blk. ____ Sub. Name ____

4. Use
(●)Domestic ( )Municipal ( )Monitor ( )Irrigation
( )Thermal ( )Injection ( )Other ____

5. TYPEOF WORK check all that apply (Replacement etc.)
(●)New Well ( ) Modify ( )Abandonment ( )Other ____

6. DRILL METHOD
(●)Air Rotary ( )Cable Tool ( )Mud Rotary ( )Other ____

7. SEALING PROCEDURES

SEAL / FILTER PACK Material	From	To	AMOUNT Sacks or pounds	Method
Bentonite Slurry	0	18'	6 sacks	Overbore

Was drive shoe used? (●) Y ( ) N Shoe Depths(s) 88'
Was drive shoe seal tested? ( ) Y (●) N How? N/A

8. Casing / Liner

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+2	88	0.25	Steel	(●)	( )	(●)	( )
					( )	( )	( )	( )
					( )	( )	( )	( )
					( )	( )	( )	( )

Length of Headpipe N/A Length of Tailpipe N/A

9. PERFORATIONS / SCREENS
Perforations Method N/A
Screens Screen Type Stainless

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
88'	93'	20	N/A	6"	Stainless	( )	( )
						( )	( )
						( )	( )

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE
69 ft. below ground Artesian pressure N/A lb.

Depth flow encountered N/A ft. Describe access port or control devices: N/A

11. WELL TESTS
( )Pump ( )Bailer ( )Air ( )Flowing

Yield Gal. / Min.	Drawdown	Pumping Level	Time
25		93'	1 Hour

Water Temp. 52 Bottom Hole Temp. ____
Water Quality test or comments: Good
Depth first Water 47'

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
10	0	6	TOPSOIL		✓
10	6	18	SAND & GRAVEL		✓
6	18	34	SAND & GRAVEL		✓
6	34	47	CLAY - BROWN		✓
6	47	81	SAND BROWN FINE	✓	
6	81	93	SAND & GRAVEL	✓	

RECEIVED
SEP 10 2008
IDWR/North

Completed Depth 93' (Measurable)
Date Started 7-29-08 Completed 7-30-08

13. DRILLER'S CERTIFICATION
I/we certify that all minimum well construction standards were complelied with at the time the rig was removed.
Company Name Intermountain Drilling Firm No. 513
Firm Official and Driller or Operator [signature] Date 9-4-08
Date ____
(Sign once if Firm Official & operator)

58N 04W 17

FORWARD WHITE COPY TO WATER RESOURCES