

97-7931 EVIDENCE OF PRIORITY

BONNER COUNTY PARCEL DATA

Form 738-7
7/98
Starships Consulting and
Management Services

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only			
Inspected by _____			
Twp. _____	Rge. _____	Sec. _____	
Lat: _____	Long: _____	_____	

1. WELL TAG NO. D0056218
Drilling Permit No: 850503
Other IDWR No. _____

2. OWNER BLESSING, FRED **Well Number:** 1481
Address P.O. BOX 1043
City PRIEST RIVER State ID Zip 83856

3. LOCATION OF WELL by legal description
sketch map location must agree with written location

N				
S				

Twp. 57N ☒ North or ☐ South
Rge. 04W ☐ East or ☒ West
Sec. 32 1/4 NE 1/4 SW 1/4
Gov't Lot _____ County BONNER
Latitude: N48:14:563 Longitude: W116:51:926

Address of Well Site Off Gunsmoke Road
City PRIEST RIVER
(Give at least name of road + Distance to Road or Landmark)
Lt. _____ Blk. _____ Sub. Name LECLAIR SUBDIVI

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____
5. TYPE OF WORK check all that apply (Replacement, etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD
☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK	AMOUNT	METHOD
Material	From To Sacks or Pounds	
BENTONITE	0 18 550 LBS	DRY POUR

Was drive shoe used? ☐ Y ☒ N Shoe Depth(s) RB
Was drive shoe seal tested? ☐ Y ☒ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	+2	114	.250	STEEL	☒	☐	☒	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
115	120	12	1	6	SS	☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
45 ft. below ground Artesian pressure _____ lb.
Depth flow encounter 100 ft. Describe access port or control devices: _____

57N 04W 32

11. WELL TESTS:
☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
8 - 10	100	120	1 HR

Water Temp. COLD Bottom Hole Temp COLD
Water Quality test or comments: CLOUDY
Depth first Water encountered 25

12. LITHOLOGIC LOG:(Describe repairs or abandonment)

Remarks: Lithology, Water Quality, Temperature				Water	
				Y	N
10	0	8	Limey Soil w/ Gravel	☐	☒
10	8	10	Boulder	☐	☒
10	10	12	Limey Soil w/ Gravels	☐	☒
10	12	18	Blue Silt w/ Clay Seems	☐	☒
8	18	28	Blue Silt w/ Clay Seems Wet	☒	☐
8	28	86	Cemented Sand & Gravels	☐	☒
8	86	102	Fine Sand Wet	☒	☐
8	102	120	Sands w/ Small Gravels 10gpm apx	☒	☐

RECEIVED

JUL 06

IDWR/North

RECEIVED

JUL 06 2009

IDWR/North

Completed Depth 120 (Measurable)
Date: Started 6/2/2009 Completed 6/3/2009

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name H2O WellService, Inc. Firm No. 448
Firm Official [Signature] Date 6-11-09
and _____
Supervisor or Operator [Signature] Date 6/8/2009
LOUIE HANNER (Sign once if Firm Official and Operator)

Aerial imagery of parcel no. RP042030000020A showing recreational camping structures.

