

97-9118 EVIDENCE OF PRIORITY

BONNER COUNTY PARCEL DATA

Field	Value
ACRES	4.6
ADDRESS1	91 EVERGREEN LN
ADDRESS2	
BackfillFr	
CITY	PRIEST RIVER
COUNTY	Bonner
FID	226
LEGAL1	8-57N-4W EVERGREEN ACRES 1999 LIBERTY 14 X 56 VIN 09L32935 TITLE 98981161
LEGAL2	
LEGAL3	
LEGAL4	
LEGAL5	
LEGAL6	
OWNER	MONTEITH, LAURISTON & RUBY
OwnerFromA	
OwnerFromI	
P_ADDRESS	ID
P_ZIPCODE	83856
PIN	MH0069700004B0A
Previous_T	MONTEITH, LAURISTON & RUBY
Shape	Polygon
Shape_Area	18673.234803
Shape_Leng	577.025703
SOURCE	
StandardAd	
STATE	ID
SUB_NAME	EVERGREEN ACRES
TempUnique	227
UPDATED	8/14/2018
YEAR_BUILT	1999
ZIPCODE	83856

Form 11/97
JUN 30 1998

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

78225

Office Use Only
Inspected by _____
Twp _____ Rge _____ Sec _____
1/4 _____ 1/4 _____ 1/4 _____
Lat: _____ Long: _____

1. WELL TAG NO. D 0003799

DRILLING PERMIT NO. 97-98-N-0020-000

Other IDWR No. _____

2. OWNER:

Name Junior & Ruby Monteith

Address 5476 Sturgeon Road

City Darrington State WA Zip 98241

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.

Tw. 57 North ☒ or South ☐
Rge. 04 East ☐ or West ☒
Sec. 08 1/4 NW 1/4 SW 1/4
Gov't Lot _____ County Bonner
Lat: _____ Long: _____
Address of Well Site Evergreen Lane
off East River Road City Priest River
(Give at least name of road + Distance to Road or Landmark)

Lt. 4B Bk. _____ Sub. Name Evergreen Acres

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK	AMOUNT	METHOD
Material From To	Sacks or Pounds	
Bentonite 0 19	3sacks	Overbore

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) _____

Was drive shoe seal tested? ☐ Y ☐ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+1	114'	250	steel	☒	☐	☒	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS

Perforations Method _____
Screens Screen Type Telescoping

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
110	113	16		6"	stainless	☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

40 ft. below ground Artesian pressure _____ lb.

Depth flow encountered 85 ft. Describe access port or control devices: welded well cap

11. WELL TESTS:

☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
10gpm		115'	1hr

Water Temp. 53 Bottom hole temp. _____

Water Quality test or comments: clear

Depth first Water Encounter 85'

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
10	0	12	Sand & gravel		x
10	12	19	Fine sand		x
6	19	37	Fine sand		x
6	37	58	Clay/gray		x
6	58	85	Clay w/fine sand lenses		x
6	85	86	Sand w/fine sand	x	
6	86	97	Clay/firm		x
6	97	110	Quick sand		x
6	110	115	Sand w/fine sand @10gpm	x	

Completed Depth 115' (Measurable)
Date: Started 6-26-97 Completed 6-27-98

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Intermountain Drilg. Firm No. 513

Firm Official _____ Date 6-29-98

and _____
Driller or Operator _____ Date 6-29-98

(Sign once if Firm Official & Operator)

57N 4W 8

FORWARD WHITE COPY TO WATER RESOURCES